



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : **TP / 21005-08/MY / 2021**
Date of Report : **15 Sep 2021**

Foong Weng Sum
Blk 204C Compassvale Drive
#10-427
Singapore 543204

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 30 Aug 2021

Workshop Address : Merlin Motor & Engineering Works
No.10 Ang Mo Kio Industrial Park 2A
#03-13 AMK Auto Point
Singapore 568047

As per your instruction dated **31 Aug 2021** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SGP 3132 R**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SGP 3132 R	Engine No	: FA20A894743
Model	: Subaru Forester	Mileage	: 127949
Year / Capacity	: 2016/1998	Colour	: Grey
Chassis No	: JF1SJGK85GG069690		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 225/55 R18	Bridgestone	6.00	mm	Sport
REAR O/S	: 225/55 R18	Bridgestone	6.00	mm	Sport
FRONT N/S	: 225/55 R18	Bridgestone	6.00	mm	Sport
REAR N/S	: 225/55 R18	Bridgestone	6.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the o/s front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.

5. Enclosed number of photograph : 89 copies.

6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SGP 3132 R**
 Report No: **TP/ 21005-08/MY / 2021**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front o/s headlamp	Damage	\$ 2380.00	\$ 2380.00
1	Front o/s headlamp panel	Damage	\$ 85.00	\$ 85.00
1	Front o/s headlamp lower bracket	Damage	\$ 40.10	\$ 40.10
1	Front bumper	Damage	\$ 660.30	\$ 660.30
1	Front bumper o/s side retainer	Necessary	\$ 12.60	\$ 12.60
1	Front air intake duct	Damage	\$ 56.05	\$ 56.05
1	Front o/s fender	Damage	\$ 300.00	\$ 300.00
1	Front o/s fender inner shield	Damage	\$ 96.05	\$ 96.05
1	Front o/s fender inner shield clip (1 set)	Necessary	\$ 45.00	\$ 45.00
1	Front o/s shock absorber	Damage	\$ 360.00	\$ 360.00
1	Front o/s wheel hub c/w bearing	Damage	\$ 270.00	\$ 270.00
1	Front o/s knuckle arm	Damage	\$ 300.00	\$ 300.00
1	Front o/s lower arm	Damage	\$ 548.00	\$ 548.00
1	Front stabilizer bar o/s link	Damage	\$ 82.80	\$ 82.80
			<u>\$ 5235.90</u>	<u>\$ 5235.90</u>
	Discount	20.0%	\$ 1047.18	\$ 1047.18
			<u>\$ 4188.72</u>	<u>\$ 4188.72</u>
<u>Special Nett Items</u>				
1	Front o/s tyre (depreciation)	Damage	\$ 350.00	\$ 210.00
1	Front o/s sport rim	Damage	\$ 700.00	\$ 700.00
			<u>\$ 1050.00</u>	<u>\$ 910.00</u>

Spare Parts Total \$ 5238.72 \$ 5098.72

Vehicle No: **SGP 3132 R**
Report No: **TP/ 21005-08/MY / 2021**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 5238.72	\$ 5098.72
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 80.00	\$ 50.00
2	To remove and refit front undercarriage.	\$ 300.00	\$ 200.00
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 200.00	\$ 120.00
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1100.00	\$ 750.00
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1100.00	\$ 750.00
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 60.00
Total		<u>\$ 8118.72</u>	<u>\$ 7028.72</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 5600.00

SDLS: FIVE THOUSAND SIX HUNDRED ONLY


Qualified Appraiser





























































