



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2201334

INV Date 11/03/2022

Reference CC4/LPC21012272/Kpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5965S
Insured Veh. GBC 8111X
Claim No. 21/21/21/VC00/025176
Policy No. Z/21/VC00/110352
Accident Date 20/11/2021
Inspection Date 06/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21012272/Kpa3q2 Date: 11/03/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 8111X	Veh. Inspected	SHD 5965S	
Policy No.	Z/21/VC00/110352	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/025176	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	03/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FU703075517	Colour	M . P. WHITE / RED	
Odometer	299678 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	SAILUN	8 mm	
L/H Front Tyre	195/65 R15	SAILUN	8 mm	
R/H Rear Tyre	195/65 R15	SAILUN	6 mm	
L/H Rear Tyre	195/65 R15	SAILUN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2021	Inspection Date	06/12/2021	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5965S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HOOD SUB-ASSY	TO REPAIR SEE LABOUR	983.10	-
1	HINGE ASSY ,HOOD ,LH	TO REPAIR SEE LABOUR	58.90	-
1	HINGE ASSY ,HOOD ,RH	TO REPAIR SEE LABOUR	58.90	-
1	LOCK ASSY ,HOOD	TO REPAIR SEE LABOUR	135.00	-
1	COVER ,FRONT BUMPER	BUCKLED	516.00	516.00
1	ABSORBER ,FRONT BUMPER ENERGY	SERVICEABLE	79.60	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	332.70	-
1	UNIT ASSY ,HEADLAMP ,LH	MTG CRACKED	2,637.60	2,637.60
1	UNIT ASSY ,HEADLAMP ,RH	MTG CRACKED	2,637.60	2,637.60
1	GRILLE SUB-ASSY ,RADIATOR	DISTORTED	346.00	346.00
1	EMBLEM ASSY ,RADIATOR GRILLE	CRACKED	90.80	90.80
1	GRILLE ,RADIATOR LOWER NO.1	DISTORTED	170.10	170.10
	LESS 25% DISCOUNT		-2,011.58	-1,599.53
			6,034.72	4,798.57
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	90.00	50.00
1	FRT NUMBER PLATE WITH MOULDING (SN)	DENTED	200.00	45.00
1	FRT BUMPER SIDE RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
			365.00	95.00
<u>LABOUR</u>				
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF HOOD SUB-ASSY ,HINGE ASSY ,HOOD ,LH ,HINGE ASSY ,HOOD ,RH,LOCK ASSY ,HOOD AND REAR BUMPER REINFORCEMENT .		3,000.00	200.00
	TO RUST -PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .	NOT NECESSARY	240.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,600.00	220.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
			5,610.00	440.00
GRAND TOTAL			12,009.72	5,333.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CC4/LPC21012272/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5965S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5965S

RE-INSPECTION

