

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012274/APA3Q2**Date:** 11/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070036881
Claimant Vehicle No :	SLN8606J	Insured Vehicle No :	SGL609Z
Date of Loss:	27/11/2021	Nature of Claim:	TP
		Claim No:	3556455937SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8606J	Engine No:	M16A2029688
Make & Model:	SUZUKI SWIFT, 1.6 Sport (M)	Chassis No:	JSAFZC32S00400026
Reg. Date:	19/05/2017 (Man. Year: 2015)	Odometer:	98104 km
Colour:	Grey		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,082.00	492.14	1,589.86	76.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	530.00	620.00	53.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,232.00	1,022.14	2,209.86	68.37
Approved Total (Overridden) (\$\$)		800.00		
Nett Amount (\$\$)	3,232.00	800.00	2,432.00	75.25
+ Loss of Use (2.0 x S\$60.00/day) (\$\$)		120.00		
Nett Liability (\$\$)		920.00		
Global Sum Settlement (\$\$)		920.00		

INSPECTION

Date of Assignment:	01/12/2021	
Date Inspected:	01/12/2021	Inspected At: Advance Auto Garage 10 Kaki Bukit Road 2, #01-21 First East Centre Singapore 417868
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	2		*REAR NUMBER PLATE LAMP	Not Necessary	90.00 F	*- FL
3	1		*REAR BUMPER	Repair	637.60 F	*- FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	76.00 F	*- FL
6	1		*REAR BUMPER LOWER GARNISH	Deformed	308.40 F	*308.40 FL
7	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
8	2		*TAILLAMP	Not Necessary	630.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,082.00	538.40
- List Item Discount on L Items 0.00/15.00% (S\$)	0.00	46.26
Total Parts (S\$)	2,082.00	492.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	600.00	250.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			1,150.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >