

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21012278/AQCN2**Date:** 17/04/2022**REFERENCE**

Insured/Claimant: EZEKIEL PAUL JAMES EMMANUEL  
Date of Loss: 01/12/2021

Policy No: 2070162597  
Nature of Claim: OD Claim No: 5871813265SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SFY806P**  
Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A) Engine No: DEM026746  
Reg. Date: 17/11/2020 (Man. Year: 2020) Chassis No: WAUZZZF42MA011901  
Colour: Blue Odometer: 15588 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$185,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17  
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	23,629.00	14,311.28	9,317.72	39.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,132.00	12,987.00	8,145.00	38.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,761.00</b>	<b>27,298.28</b>	<b>17,462.72</b>	<b>39.01</b>
<b>- Excess (S\$)</b>	1,100.00	1,100.00	0.00	0.00
<b>(S\$)</b>	43,661.00	26,198.28	17,462.72	40.00
<b>+ GST 7.00/7.00% (S\$)</b>	3,056.27	1,833.88	1,222.39	40.00
<b>Nett Amount (S\$)</b>	<b>46,717.27</b>	<b>28,032.16</b>	<b>18,685.11</b>	<b>40.00</b>

**INSPECTION**

Date of Assignment: 03/12/2021

Date Inspected: 02/12/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 15.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-RH	Repair	1,092.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
3	1		*FRONT FENDER BRACE-RH	Not Necessary	118.00 FS	*- FS
4	1		*FRONT FENDER BRACE COVER-RH	Not Necessary	31.00 FS	*- FS
5	1		*HEADLAMPS COVER-RH	Not Necessary	44.00 FS	*- FS
6	1		*FRONT DOOR-RH	Dented	3,192.00 FS	*2,553.60 FS
7	1		*FRONT DOOR OUTER SEAL-RH	Necessary	205.00 FS	*164.00 FS
8	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
9	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
10	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
11	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	1,050.00 FS	*- FS
12	1		*FRONT DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
13	1		*FRONT DOOR CATCH TRIM PLATE-RH	Repair	88.00 FS	*- FS
14	1		*FRONT DOOR MOUNTING BAR-RH	Not Necessary	164.00 FS	*- FS
15	1		*FRONT WINDOW REGULATOR-RH	Not Necessary	282.00 FS	*- FS
16	1		*FRONT WING MIRROR MOUNTING-RH	Cut	1,089.00 FS	*871.20 FS
17	1		*FRONT WING MIRROR CAP-RH	Missing	289.00 FS	*231.20 FS
18	1		*FRONT WING MIRROR GLASS-RH	Cut	1,667.00 FS	*1,333.60 FS
19	1		*FRONT WINDOW SLOT SEAL TRIM STRIP-RH	Not Necessary	307.00 FS	*- FS
20	1		*FRONT WINDOW GUIDE TRIM STRIP	Cut	257.00 FS	*205.20 FS
21	1		*FRONT DOOR WINDOW-RH	Not Necessary	290.00 FS	*- FS
22	1		*FRONT TYRE PRESSURE DATA PLATE	Necessary	38.00 FS	*31.28 FS
23	1		*REAR DOOR-RH	Dented	3,192.00 FS	*2,553.60 FS
24	1		*REAR DOOR OUTER SEAL-RH	Necessary	205.00 FS	*164.00 FS
25	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
26	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
27	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
28	1		*REAR DOOR SEALING STRIP	Not Necessary	17.00 FS	*- FS
29	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	860.00 FS	*- FS
30	1		*REAR DOOR CATCH-RH	Not Necessary	120.00 FS	*- FS
31	1		*REAR DOOR MOUNTING BAR-RH	Not Necessary	164.00 FS	*- FS
32	1		*REAR DOOR HANDLE TRIM PLATE-RH	Missing	88.00 FS	*69.92 FS
33	1		*REAR DOOR HOUSING-RH	Damaged	8.00 FS	*5.92 FS
34	1		*REAR DOOR COVER-RH	Damaged	6.00 FS	*4.64 FS
35	1		*REAR DOOR HANDLE SENSOR-RH	Damaged	228.00 FS	*182.40 FS
36	1		*REAR DOOR HANDLE-RH	Not Necessary	44.00 FS	*- FS
37	1		*REAR PERIPHERAL LIGHT-RH	Not Necessary	72.00 FS	*- FS
38	1		*FRONT UNDERLAY-RH	Not Necessary	4.00 FS	*- FS
39	1		*REAR UNDERLAY-RH	Not Necessary	4.00 FS	*- FS
40	1		*REAR FENDER-RH	Dented	4,052.00 FS	*3,241.60 FS
41	1		*REAR WINDOW	Necessary	1,154.00 FS	*923.20 FS
42	1		*REAR SIDE WINDOW-RH	Necessary	656.00 FS	*524.40 FS
43	2		*PRIMER	Necessary	40.00 FS	*31.52 FS
44	1		*INSERT	Necessary	89.00 FS	*71.04 FS
45	1		*REAR WHEEL HOUSING LINER-RH	Not Necessary	240.00 FS	*- FS
46	1		*ACYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
47	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
48	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
49	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
50	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
51	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
52	1		*SUNDRIES	Necessary	500.00 FS	*32.72 FS
53	1		*CORNER TRIM - RH	Cut	46.00 FS	*36.24 FS

(Supplementary)

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)    23,629.00    14,311.28**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	700.00	560.00
3	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
4	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OR RHS REAR FENDER	New	600.00	600.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN,1/4 GLASS AND RHS FRONT DOOR WINDOW GLASS	New	400.00	400.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
8	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENTS TRIMS.DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
9	TO DISMANTLE AND REINSTALL FRONT BUMPER AND REAR BUMPER.TO CUT OUT AND WELD RHS REAR FENDER.TO RENEW RHS FRONT FENDER,RHS FRONT DOOR AND RHS REAR DOOR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	7,700.00	4,000.00
10	TO RESPRAY REAR BUMPER,RHS FRONT FENDER,RHS FRONT DOOR,RHS WING MIRROR COVER,DOOR HANDLES,RHS REAR DOOR,RHS REAR FENDER,RHS SILL PANEL,DRAIN CHANNEL,DOOR ENTRANCE,ROOF CHANNEL AND REAR END PANELLING	New	7,700.00	3,925.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>21,132.00</b>	<b>12,987.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >