

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21012279/EQY3E2

Date: 28/12/2021

REFERENCE

Insured/Claimant:	SH COGENT LOGISTICS PTE LTD	Policy No:	DMCVSNA00147682100	Claim No:	SNM21D206991/C01/TANKL
Date of Loss:	30/11/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE5117D	Engine No:	E13CAT10405
Make & Model:	HINO SH1EEMA-KAS, 12.9 D (M)	Chassis No:	JHDSH1EEMXXX10248
Reg. Date:	23/08/2019 (Man. Year: 2019)	Odometer:	50939 km
Colour:	Green		
Engine Capacity:	12913 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,436.00	10,093.00	6,343.00	38.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,300.00	1,100.00	45.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,836.00	11,393.00	7,443.00	39.51
Approved Total (Overridden) (S\$)		9,100.00		
- Excess (S\$)	2,500.00	2,500.00	0.00	0.00
(S\$)	16,336.00	6,600.00	9,736.00	59.60
+ GST 7.00/7.00% (S\$)	1,143.52	462.00	681.52	59.60
Nett Amount (S\$)	17,479.52	7,062.00	10,417.52	59.60

INSPECTION

Date of Assignment:	03/12/2021		
Date Inspected:	03/12/2021	Inspected At:	Vfix Auto Pte Ltd 7 Penjuru Close Level 1 Singapore 608779
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Dec 2021)	
Parts:	N/A	HINO SH1EEMA-KAS 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE5117D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL	Broken	655.00 F	*600.00 F
2	1		*FRONT CORNER PANEL LAMP	Broken	450.00 F	*400.00 F
3	1		*FRONT SIDE MIRROR BRACKET	Missing	468.00 F	*160.00 F
4	1		*FRONT SIDE MIRROR ARM LH	Not Necessary	896.00 F	*- F
5	1		*FRONT DOOR	Dented	4,898.00 F	*4,200.00 F
6	1		*FRONT DOOR (EURO 6) STICKER	Necessary	189.00 F	*120.00 F
7	1		*FRONT DOOR OUTER LOWER MOULDING	Broken	368.00 F	*368.00 F
8	1		*FRONT DOOR OUTER LOWER INNER FRAME	Not Necessary	898.00 F	*- F
9	1		*FRONT DOOR SIGNAL LAMP	Broken	210.00 F	*150.00 F
10	1		*FRONT DOOR HINGE (2PCS)	Bent (1Pc Only)	470.00 F	*200.00 F
11	1		*FRONT DOOR CHECKER	Not Necessary	325.00 F	*- F
12	1		*FRONT DOOR INNER LOCK	Bent	792.00 F	*380.00 F
13	1		*FRONT DOOR TRIM LH	Broken	1,568.00 F	*820.00 F
14	1		*FRONT DOOR LINKAGE	Bent	789.00 F	*500.00 F
15	1		*SIDE STEP COVER LH	Broken	385.00 F	*385.00 F
16	1		*FRONT DOOR LH SIDE RUBBER	Torn	415.00 F	*310.00 F
17	1		*FRONT CORNER PANEL LH INNER	Bent	1,156.00 F	*750.00 F
18	1		*FRONT DOOR PILLAR WEATHER STRIP LH	Torn	815.00 F	*300.00 F
19	1		*FOOT STEP UPPER GARNISH LH	Broken	689.00 F	*450.00 F
Total Parts (S\$)						16,436.00
						10,093.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS / ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR, REPAIR / RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS / ATTACHMENT	New	1,200.00	500.00
2	TO SPRAY PAINT REPLACED / REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	700.00
3	TO CHECK, DIAGNOSIS, TROUBLE SHOOT, RESET ALL THE WIRING FAULT CODE	New	120.00	50.00
4	TO REPLACE ALL THE ITEM ABOVE	New	80.00	50.00
Gross Labour Cost (\$\$)			2,400.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >