



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3985Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER COVER	CUT	430.90	430.90
1	FRONT BUMPER BRACKET LH	NECESSARY	35.00	35.00
1	HEADLAMP LH	SERVICEABLE	1,993.60	-
1	FRONT BUMPER MOULDING CENTRE UPPER E RH	SERVICEABLE	368.50	-
1	DAY LIGHT LH	SERVICEABLE	642.50	-
1	FRONT BUMPER GRILLE LH	SERVICEABLE	186.90	-
1	FRONT WHEEL HUB COVER LH (SERVICEABLE)	NOT CONSISTENT WITH THE IMPACT	346.40	-
	LESS 20% DISCOUNT		-800.76	-93.18
			3,203.04	372.72
<u>LABOUR</u>				
	PANEL BEATING.		520.00	350.00
	SPRAY PAINT.		600.00	500.00
	RESET FRONT WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.		60.00	20.00
			1,240.00	870.00
GRAND TOTAL			4,443.04	1,242.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,000.00

Report Ref No. NS/INC21012281/Vuce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.