



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 7100X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOT LID	NOT NECESSARY	503.90	-
1	BOOT LID TOP LOCK	SERVICEABLE	78.90	-
1	BOOT LID WEATHERSTRIP	RIPPED / NECESSARY	87.90	87.90
1	BOOT LID LOWER LOCK	SERVICEABLE	35.00	-
2	BOOT LID HINGE @\$43.20	REUSE	86.40	-
1	BOOT LID OUTER MOULDING GARNISH	SERVICEABLE	125.80	-
1	BOOT LID LOGO	SERVICEABLE	33.00	-
1	BOOT LID EMBLEM 'VTEC'	SERVICEABLE	30.60	-
1	BOOT LID EMBLEM 'CITY'	SERVICEABLE	34.50	-
1	REAR BUMPER	DEFORMED / CRACKED	589.00	463.70
2	REAR BUMPER SIDE RETAINER @\$22.70	NECESSARY	45.40	45.40
2	REAR TAIL LAMP @\$310.00	NOT NECESSARY	620.00	-
2	REAR TAIL LAMP PANEL @\$59.40	TO REPAIR SEE LABOUR	118.80	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	419.60	-
1	REAR END PANEL TOP GARNISH	REUSE	80.50	-
	LESS 20% DISCOUNT		-577.86	-119.40
			2,311.44	477.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
10	REAR BUMPER CLIPS @\$5.00 (SN)	NECESSARY	50.00	25.00
2	REAR TAIL LAMP CLIPS @\$5.00 (SN)	NOT NECESSARY	10.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	MALFUNCTION	250.00	200.00
			400.00	225.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL AND REAR END PANEL.		855.00	400.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		900.00	400.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		50.00	30.00
	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING.		76.50	30.00
	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORK.	NOT NECESSARY	45.00	-
	WIRING AND BULB CHECKING.		36.00	20.00
			1,962.50	880.00
	<b>GRAND TOTAL</b>		<b>4,673.94</b>	<b>1,582.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,250.00</b>

Report Ref No. CS3/AIG21006188/Bvf3n2-1

LIM TEOW GUAN

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.