

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012294/EVF3E2**Date:** 07/02/2022**REFERENCE**

Insured/Claimant: CHUA TECK YONG,DANIEL (CAI DERONG) DANIEL Policy No: 1900017303
Date of Loss: 03/12/2021 Nature of Claim: OD Claim No: 2140183711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ1769C**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH702498
Reg. Date: 25/02/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5009871
Colour: White Odometer: 57836 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Nexen 4 mm Rear Left Side: Nexen 4 mm
Front Right Side: Nexen 4 mm Rear Right Side: Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,109.00	7,061.00	2,048.00	22.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,330.00	5,730.00	2,600.00	31.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,439.00	12,791.00	4,648.00	26.65
+ GST 7.00/7.00% (S\$)	1,220.73	895.37	325.36	26.65
Nett Amount (S\$)	18,659.73	13,686.37	4,973.36	26.65

INSPECTION

Date of Assignment: 06/12/2021
Date Inspected: 06/12/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Broken	675.00 FL	*675.00 FL
2	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Cut	675.00 FL	*675.00 FL
3	1		*LAMP ASSY-REAR COMB INSIDE, LH	Broken	608.00 FL	*608.00 FL
4	1		*LAMP ASSY-REAR COMB INSIDE, RH	Broken	608.00 FL	*608.00 FL
5	1		*LAMP ASSY-CENTER GARNISH	Broken	690.00 FL	*690.00 FL
6	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
7	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
8	1		*HINGE ASSY-TRUNK LID, LH	Bent	97.00 FL	*97.00 FL
9	1		*HINGE ASSY-TRUNK LID, RH	Bent	97.00 FL	*97.00 FL
10	1		*PANEL & FRAME ASSY-PKG TRAY, RR	Not Necessary	312.00 FL	*- FL
11	1		*PANEL ASSY-REAR FLOOR, RR	Dented	219.00 FL	*219.00 FL
12	1		*PANEL ASSY-QUARTER OUTER, LH	Repair	1,349.00 FL	*- FL
13	1		*PANEL ASSY-COMB LAMP HSG, LH	Dented	139.00 FL	*139.00 FL
14	1		*MAT ASSY-LUGAGGE COVERING	Broken	211.00 FL	*211.00 FL
15	1		*TRIM ASSY-RR TRANSVERSE	Crushed	41.00 FL	*41.00 FL
16	1		*GLASS ASSY-REAR WINDOW	Not Necessary	447.00 FL	*- FL
17	10		*PAD-WINDSHIELD GLASS	Not Necessary	20.00 FL	*- FL
18	2		*STOPPER-GLASS	Not Necessary	8.00 FL	*- FL
19	4		*TERMINAL-RR WDO GLASS DEFOGGER	Not Necessary	16.00 FL	*- FL
20	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
21	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
22	1		*COVER-RR BUMPER UNDER, LH	Broken	33.00 FL	*33.00 FL
23	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
24	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
25	1		*COVER-RR BUMPER FOG LAMP, LH	Cut	19.00 FL	*19.00 FL
26	1		*COVER-RR BUMPER FOG LAMP, RH	Cut	19.00 FL	*19.00 FL
27	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
28	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
29	1		*EXTN WIRING ASSY-BWS	Broken	207.00 FL	*207.00 FL
30	1		*BRACKET-RR BEAM UPR MTG, LH	Broken	9.00 FL	*9.00 FL
31	1		*BRACKET-RR BEAM UPR MTG, RH	Broken	9.00 FL	*9.00 FL
32	1		*BRACKET-RR BEAM LWR, CTR	Crushed	6.00 FL	*6.00 FL
33	1		*BRACKET-RR BEAM LWR MTG	Crushed	6.00 FL	*6.00 FL
34	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
35	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
36	1		*STAY-RR BUMPER LH	Dented	65.00 FL	*65.00 FL
37	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Broken	25.00 FL	*25.00 FL
38	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Broken	31.00 FL	*31.00 FL
39	1		*STAY-RR BUMPER RH	Dented	65.00 FL	*65.00 FL
40	1		*BRACKET ASSY-SPARE TIRE MTG	Necessary	15.00 FL	*15.00 FL
			(Supplementary)			
41	1		*REINF-RR SPARE TIRE WELL CROSS	Necessary	41.00 FL	*41.00 FL
			(Supplementary)			
42	1		*HOOK-TOWING	Necessary	16.00 FL	*16.00 FL
			(Supplementary)			
43	1		*REINF-TOWING HOOK	Necessary	14.00 FL	*14.00 FL
			(Supplementary)			
44	1		*TRIM ASSY-LUGGAGE SIDE LH	Crushed	200.00 FL	*200.00 FL
			(Supplementary)			
45	1		*TRIM ASSY-LUGGAGE SIDE RH	Crushed	200.00 FL	*200.00 FL
			(Supplementary)			
46	10		*FASTENER	Necessary	10.00 FL	*10.00 FL
			(Supplementary)			
47	1		*TRIM ASSY-TRUNK LID	Crushed	202.00 FL	*202.00 FL
			(Supplementary)			
48	1		*LATCH ASSY-TRUNK LID	Bent	112.00 FL	*112.00 FL
			(Supplementary)			
49	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
			(Supplementary)			

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*PLUS (Supplementary)	Necessary	2.00 FL	*2.00 FL
51	1		*PLUG-DRAINE HOLE (Supplementary)	Necessary	5.00 FL	*5.00 FL
52	1		*PANEL ASSY-RR COMB LAMP HSG, RH (Supplementary)	Dented	135.00 FL	*135.00 FL
53	15		*CLIPS (Supplementary)	Necessary	15.00 FL	*15.00 FL
54	1		*SILENCER, FLOOR (Supplementary)	Necessary	13.00 FL	*13.00 FL
55	1		*K3 BOOT LIP SPOILER (Supplementary)	Broken	211.00 FS	*211.00 FS
56	1		*SUNDRIES (Supplementary)	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,326.00	8,766.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,217.00	1,705.00
Total Parts (\$)	9,109.00	7,061.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, BOOT, END PANEL, SPARE TYRE PANEL, REAR LH FENDER REAR LH HEADLAMP PANEL & AFFECTED AREA	New	3,600.00	2,000.00
2	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, SPARE TYRE PANEL, REAR LH FENDER & LH TAIL LAMP PANEL	New	2,100.00	1,750.00
3	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	80.00	80.00
4	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
5	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	120.00	120.00
6	REMOVE & REPLACE REAR WINDSCREEN GLASS	New	240.00	0.00
7	TO APPLY WINDSCREEN SEALANT	New	80.00	0.00
8	TO SUPPLY WINDSCREEN SOLAR FILM	New	220.00	0.00
9	TO TRANSFER BOOT COMPARTMENT TO NEW PANEL	New	120.00	120.00
10	REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR	New	400.00	400.00
11	TO APPLY SEALANT ON AFFECTED AREA	New	120.00	80.00
12	PERFORM RUST PREVENTION	New	80.00	40.00
13	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
14	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
15	TO SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	50.00
16	TO SUPPLY C&C EMBLEM	New	50.00	20.00
17	REPLACE REAR FLOOR PANEL (Supplementary)	New	800.00	800.00
Gross Labour Cost (\$\$)			8,330.00	5,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >