

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012297/EQF3E2**Date:** 07/02/2022**REFERENCE**

Insured/Claimant: PEK BAN HUA (BAI WANHUA) Policy No: 2070052758
Date of Loss: 04/12/2021 Nature of Claim: OD Claim No: 2473913379SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG6661K**
Make & Model: KIA SORENTO, 2.2 (A) Engine No: G4JKH776008
Reg. Date: 20/03/2020 (Man. Year: 2019) Chassis No: KNAPH813ML5636133
Colour: Grey Odometer: 20067 km
Engine Capacity: 2359 cc
Market Value/New Car Price: S\$165,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Nexen 4 mm Rear Left Side: Nexen 4 mm
Front Right Side: Nexen 4 mm Rear Right Side: Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,550.40	3,677.60	1,872.80	33.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	3,310.00	2,690.00	44.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,550.40	6,987.60	4,562.80	39.50
+ GST 7.00/7.00% (S\$)	808.53	489.13	319.40	39.50
Nett Amount (S\$)	12,358.93	7,476.73	4,882.20	39.50

INSPECTION

Date of Assignment: 06/12/2021
Date Inspected: 06/12/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*PANEL ASSY-FRONT DOOR, LH	Dented	1,582.00 FL	*1,582.00 FL
3	2		*HINGE ASSY-FRONT DOOR, LH	Not Necessary	64.00 FL	*- FL
4	1		*W/STRIP ASSY-FR DR BELT O/S LH	Not Necessary	95.00 FL	*- FL
5	1		*GARNISH ASSY-FNDR SIDE, LH	Not Necessary	88.00 FL	*- FL
6	1		*GARNISH ASSY-FRT DR SIDE, LH	Missing	204.00 FL	*204.00 FL
7	1		*GARNISH ASSY-RR DR SIDE LH	Missing	242.00 FL	*242.00 FL
8	1		*GARNISH ASSY-QTR SIDE, LH	Not Necessary	49.00 FL	*- FL
9	1		*PANEL ASSY-REAR DOOR, LH	Dented	1,290.00 FL	*1,290.00 FL
10	1		*HINGE ASSY-REAR DOOR UPPER, LH	Not Necessary	33.00 FL	*- FL
11	1		*HINGE ASSY-REAR DOOR LOWER, LH	Not Necessary	33.00 FL	*- FL
12	1		*GARNISH ASSY-RR DR RR FRAME, LH	Not Necessary	85.00 FL	*- FL
13	1		*GARNISH ASSY-RR DR FR FRAME, LH	Not Necessary	98.00 FL	*- FL
14	1		*W/STRIP ASSY-RR DR BELT O/S RH	Not Necessary	81.00 FL	*- FL
15	1		*FILM-RR DR ANTI CHIPPING, LH	Necessary	11.00 FL	*11.00 FL
16	1		*WHEEL ASSY-ALUMINIUM LHR	Cut	689.00 FL	*689.00 FL
17	1		*CARRIER ASSY-REAR AXLE LH	Not Necessary	509.00 FL	*- FL
18	1		*HUB ASSY-RR WHEEL LHR	Not Necessary	530.00 FL	*- FL
19	1		*SHOCK ABSORBER ASSY-REAR	Not Necessary	297.00 FL	*- FL
20	1		*BRACKET-SHOCK ABSORBER MTG	Not Necessary	106.00 FL	*- FL
21	1		*ARM ASSY-RR TRAILING ARM, LH	Not Necessary	175.00 FL	*- FL
22	1		*ARM ASSY-RR ASSIST	Bent	240.00 FL	*240.00 FL
23	1		*ARM & BUSH ASSY-SUSP UPR	Bent	159.00 FL	*159.00 FL
24	1		*GARNISH ASSY-DR FRAME LH	Not Necessary	98.00 FL	*- FL
25	1		*MOULDING ASSY-SIDE SILL, LH	Cut	141.00 FL	*141.00 FL
26	1		*BOLT (Supplementary)	Bent	14.00 FL	*14.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,933.00	4,592.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,382.60	914.40
Total Parts (\$\$)	5,550.40	3,677.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	X-MEMBER REAR (NPA)	New	0.00	0.00
2	RENEW LHF DOOR & LHR DOOR. REPAIR LH ROCKER PNL & LH CENTRE PILLAR PNL	New	2,400.00	1,200.00
3	RESPRAY LHF DOOR, LHR DOOR, LH ROCKER PNL & LH CENTRE PILLAR PNL	New	1,400.00	1,050.00
4	REMOVE & REFIT LHF DOOR COMPONENT	New	120.00	120.00
5	REMOVE & REFIT LHR DOOR COMPONENT	New	120.00	120.00
6	RENEW LHR SPORT RIM & TRANSFER TYRE	New	30.00	30.00
7	SUPPLY LHR TYRE-NEXEN	New	580.00	0.00
8	REMOVE & REFIT LH TRIM & CARPET TO FACILITATE REPAIR	New	120.00	0.00
9	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
12	RENEW X-MEMBER ASSY	New	400.00	0.00
13	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
14	SUPPLY BODY PNL SEALANT	New	80.00	80.00
15	RENEW REAR U/CARRIAGE LH	New	400.00	400.00
Gross Labour Cost (\$\$)			6,000.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >