

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8679D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	CUT	1,106.00	553.00
2	REAR BUMPER BRACKET SIDE LH / RH @\$35.60	N/S NECESSARY / O/S SERVICEABLE	71.20	35.60
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER COVER	DISTORTED	228.00	228.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	BOOTLID EMBLEM I-40	NECESSARY	67.90	67.90
1	BOOTLID CDRI	NECESSARY	52.40	52.40
1	TAIL LAMP LH	MISSING	870.40	691.85
2	REAR BUMPER REFLECTOR LH / RH	CUT	32.00	32.00
1	BOOTLID LOWER PANEL	DENTED	227.90	227.90
	LESS 20% DISCOUNT		-614.52	-382.12
			2,458.08	1,528.53
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	BOOTLID ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR FENDER LH ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	CUT	135.70	135.70
			435.70	435.70
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	560.00
	SPRAY PAINTING CHARGE.		750.00	500.00
	CHECK LIGHTING.		50.00	20.00
	REMOVE / REFIX REVERSE SENSOR.		60.00	20.00
	TUFF KOTE.		60.00	20.00
			1,520.00	1,120.00
	GRAND TOTAL		4,413.78	3,084.23

Report Ref No. NS/INC21012298/Vvce2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,450.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC21012298/Vvce2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser