

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012302/EVY3N2**Date:** 18/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00005822000

**Claimant Vehicle
No :** SBQ18L**Insured Vehicle
No :** SLJ3689Z

Date of Loss: 03/10/2021

Nature of Claim: TP

Claim
No: SNM21D205988/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SBQ18L**

Make & Model: BMW M3, 3.0 (A)

Engine No: 06679378S55B30A

Reg. Date: 23/05/2016 (Man. Year: 2015)

Chassis No: WBS8M92050P972542

Colour: Black

Odometer: 68541 km

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35R19

Rear Tyre Size:

255/35R19

Front Left Side: Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,802.10	839.50	5,962.60	87.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,656.00	2,087.00	1,569.00	42.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,458.10	2,926.50	7,531.60	72.02
+ GST 7.00/7.00% (S\$)	732.07	204.86	527.21	72.02
Nett Amount (S\$)	11,190.17	3,131.36	8,058.81	72.02

INSPECTION

Date of Assignment: 17/01/2022

Date Inspected: 07/12/2021 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance
Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2022)
Parts:	143	BMW M3 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBQ18L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER TOP MOUNT	Not Necessary	380.95 FS	*- FS
2	1		*FRT SHOCK ABSORBER M ECE	Not Necessary	62.10 FS	*- FS
3	1		*INSERT AIR INLET MIDDLE	Not Necessary	106.10 FS	*- FS
4	1		*FRT BUMPER BOTTOM CARRIER	Not Necessary	355.50 FS	*- FS
5	1		*COVER,REGISTRATION PLATE	Cut	97.85 FS	*97.85 FS
6	1		*FRT BUMPER PANEL PRIMED (SRA)	Not Necessary	1,354.90 FS	*- FS
7	1		*FRT BUMPER REPAIR KIT HOLDER	Not Necessary	86.45 FS	*- FS
8	1		*GRILLE,FRONT RIGHT	Not Necessary	148.65 FS	*- FS
9	1		*GRILLE,FRONT LEFT	Not Necessary	148.65 FS	*- FS
10	2		*GROMMET	Not Necessary	1.60 FS	*- FS
11	1		*AIT DUCT RADIATOR	Not Necessary	105.90 FS	*- FS
12	1		*ADAPTER AIR DUCT (M)	Not Necessary	52.95 FS	*- FS
13	1		*PLAQUE 82MM	Necessary	71.95 FS	*71.95 FS
14	1		*RH HEADLIGHT LED AHL	Not Necessary	3,088.85 FS	*- FS
15	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
16	1		*M PERFORMANCE FRT RH GRILLE BLK	Cut	294.85 FS	*294.85 FS
17	1		*M PERFORMANCE FRT LH GRILLE (BLACK)	Cut	294.85 FS	*294.85 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,802.10	839.50
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER,FRONT CENTER AIR DUCT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,700.00	850.00
2	TO RESPRAY FRONT BUMPER	New	1,038.00	986.00
3	TO REPLACE RIGHT HEADLIGHT	New	481.00	0.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	168.00
6	TO SUPPLY FRONT EMBOSS NUMBER PLATE	New	83.00	83.00
Gross Labour Cost (\$\$)			3,656.00	2,087.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >