

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAI	NCE BHD		Ref:	CS3/LPC21012311/Gvf3e2	
	300 BEACH ROAD #17-04/07 THE CC	NCOURSESINGAPORE 199555		Date:	09/12/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	EF 5151Z	Veh. Inspected	k	SLR 8028G	
	Policy No.	Z21VP05029918	Coverage (\$)		0.00	
	Claim No.	21/21/21/VP00/025215	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		06/12/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ESTIMA 2.4	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2007	
	Chassis No.	ACR500040560	Colour		SILVER	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	ARIVO		6 mm	
	L/H Front Tyre	215/60 R16	ARIVO		6 mm	
	R/H Rear Tyre	215/60 R16	ARIVO		6 mm	
	L/H Rear Tyre	215/60 R16	ARIVO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	03/12/2021	Inspect Date /	Time	06/12/2021 ( 04:30 PM )	
	Survey held at	SHENG LI LAI				
		2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21012311/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**