

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012323/ETY3N2**Date:** 14/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00130272102

**Claimant Vehicle  
No :** SLM5373E**Insured Vehicle  
No :** GBG2910A

Date of Loss: 01/12/2021

Nature of Claim: TP

Claim  
No: SNM21D206976/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLM5373E**

Make &amp; Model: BMW 116D, 1.5 (A)

Engine No: 38149813B37D15A

Reg. Date: 31/03/2017 (Man. Year: 2016)

Chassis No: WBA1V720505G86423

Colour: White

Odometer: 86068 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Michelin 4 mm

Rear Left Side:

Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side:

Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,191.55	80.00	1,111.55	93.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,827.00	3,269.00	1,558.00	32.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,018.55</b>	<b>3,349.00</b>	<b>2,669.55</b>	<b>44.36</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	421.30	234.43	186.87	44.36
<b>Nett Amount (\$\$)</b>	<b>6,439.85</b>	<b>3,583.43</b>	<b>2,856.42</b>	<b>44.36</b>

**INSPECTION**

Date of Assignment: 06/12/2021

Date Inspected: 21/12/2021 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance  
Centre  
Singapore 159941

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2022)
<b>Parts:</b>	144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM5373E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*CLAMP	Not Necessary	33.50 FS	*- FS
2	1		*MOUNTING SUPPORT	Not Necessary	11.25 FS	*- FS
3	1		*SUPPORT CENTER	Not Necessary	17.60 FS	*- FS
4	1		*FRT BUMPER LH INSERT	Not Necessary	68.30 FS	*- FS
5	1		*FRT BUMPER RH INSERT	Not Necessary	68.30 FS	*- FS
6	1		*FRT BUMPER PANEL PRIMED	Repair	833.80 FS	*- FS
7	1		*SET PDC HOLDER FRONT	Not Necessary	25.75 FS	*- FS
8	1		*(DG/SL) ADHESVIVE SET K6	Not Necessary	53.05 FS	*- FS
9	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>1,191.55</b>	<b>80.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BUMPER FRONT PANEL.TO REMOVE AND INSTALL ATTACHMENTS ON FRONT RIGHT SIDE PANEL	New	2,550.00	1,275.00
2	TO SPRAY PAINT BUMPER FRONT PANEL AND FRONT RIGHT SIDE PANEL	New	1,923.00	1,826.00
3	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	168.00
<b>Gross Labour Cost (\$)</b>			<b>4,827.00</b>	<b>3,269.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >