

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JQR 8144

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FRONT FORK TUBE ASSY (CONSISTENT)	BENT / TWISTED	640.00	640.00
1	FORK UNDER BRACKET (CONSISTENT)	TWISTED	185.00	120.00
1	FRONT WHEEL RIM (CONSISTENT)	WARPED / BENT	380.00	380.00
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING (CONSISTENT)	NECESSARY	42.00	30.00
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	185.00	-
1	HANELE BAR (CONSISTENT)	BENT	88.00	88.00
2	HANDLE BAR ENDS (CONSISTENT)	CUT	78.00	50.00
1	SET HAND GRIP (CONSISTENT)	NOT NECESSARY	138.00	-
1	HANDLE BAR INNER BRACKET (CONSISTENT)	CRACKED	88.00	60.00
1	METER (CONSISTENT)	BROKEN	485.00	420.00
2	SET SIDE MIRRORS (CONSISTENT)	BROKEN	120.00	80.00
2	FRONT SIGNALS (CONSISTENT)	O/S CRACKED	160.00	60.00
1	FRONT SIGNAL LOWER GARNISH (CONSISTENT)	CRACKED	115.00	115.00
1	BRAKE LEVER (CONSISTENT)	BENT	48.00	48.00
1	MASTER PUMP (CONSISTENT)	NOT NECESSARY	280.00	-
1	SET FAIRING ASSY (CONSISTENT)	CRACKED	525.00	525.00
1	BASKET (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	FRONT FOOTREST BRACKET (CONSISTENT)	BENT	65.00	65.00
2	FRONT FOOTREST RUBBERS (CONSISTENT)	TORN	70.00	60.00
1	BRAKE PEDAL (CONSISTENT)	BENT	68.00	68.00
1	GEAR PEDAL (CONSISTENT)	BENT	68.00	68.00
2	REAR FOOTREST (CONSISTENT)	SERVICEABLE	80.00	-
2	REAR FOOTREST BRACKETS (CONSISTENT)	NOT NECESSARY	156.00	-
1	MAGNET HOUSING (CONSISTENT)	CRACKED	280.00	280.00
1	SIDE STAND (CONSISTENT)	TO REPAIR SEE LABOUR	70.00	-
1	MAIN STAND (CONSISTENT)	BENT	95.00	95.00
1	EXHAUST ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	685.00	-
1	EXHAUST PROTECTOR -CHROME (CONSISTENT)	BENT	78.00	78.00

Report Ref No. CC4/ASM21012325/Uga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	EXHAUST PROTECTOR -MATT BLACK (CONSISTENT)	SCRATCHED	60.00	60.00
	LESS 10% DISCOUNT		-544.20	-339.00
			4,897.80	3,051.00
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN) (CONSISTENT)	BENT / NECESSARY	38.00	20.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NECESSARY	90.00	60.00
1	STICKER (SN) (CONSISTENT)	NECESSARY	120.00	60.00
1	REAR BOX (SN) (CONSISTENT)	MISSING	380.00	200.00
1	REAR BOX BRACKET (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	180.00	-
1	E.R.P IU (LOD) (SN) (CONSISTENT)	SERVICEABLE	180.00	-
			1,074.00	340.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE (LOD).		35.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF BASKET, SIDE STAND, EXHAUST ASSY AND REAR BOX BRACKET.		420.00	380.00
	TO REPAIR BODY FRAME.	NOT NECESSARY	350.00	-
			885.00	415.00
	GRAND TOTAL		6,856.80	3,806.00

RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

1,650.00

Report Ref No. CC4/ASM21012325/Uga3q2

CHUA KANG SENG

Licensed Appraiser