

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012328/BEA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJQ1649P **Insured Vehicle No :** SLN4150H
 Date of Loss: 06/12/2021 Nature of Claim: TP Claim No: MFL2021D0005279

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ1649P**
 Make & Model: SUZUKI SX4, 1.6 (A) Engine No: M16A1463574
 Reg. Date: 27/04/2009 (Man. Year: 2009) Chassis No: JSAGYC21S00203747
 Colour: Grey Odometer: 194012 km
 Engine Capacity: 1586 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Michelin 4 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Michelin 4 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,779.42	3,111.32	3,668.10	54.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,260.00	1,490.00	54.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,529.42	4,371.32	5,158.10	54.13
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	9,529.42	3,500.00	6,029.42	63.27
+ GST 7.00/7.00% (S\$)	667.06	245.00	422.06	63.27
Nett Amount (S\$)	10,196.48	3,745.00	6,451.48	63.27
+ Car Rental (7.0 x S\$90.00/day) (S\$)		630.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,382.45		

INSPECTION

Date of Assignment: 06/12/2021
 Date Inspected: 07/12/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2022)
Parts: 144	SUZUKI SX4 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJQ1649P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	694.65 FL	*546.00 FL
2	1		*REAR BUMPER REFLECTOR R	Broken	124.10 FL	*19.00 FL
3	1		*REAR BUMPER REFLECTOR L	Broken	124.10 FL	*19.00 FL
4	2		*REAR BUMPER BRACKET	No such part	156.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Necessary	128.10 FL	*46.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Broken	269.80 FL	*215.30 FL
7	1		*REAR BUMPER LOWER CENTRE SPOILER	Dislodged	827.05 FL	*600.00 FL
8	1		*REAR BUMPER SIDE LOWER SPOILER	No such part	764.30 FL	*- FL
9	1		*TAIL LAMP L	Broken	517.20 FL	*241.85 FL
10	1		*TAIL LAMP R	Broken	517.20 FL	*241.85 FL
11	1		*REAR BOOT LID	Bent	874.20 FL	*750.00 FL
12	1		*REAR BOOT MECHANISM LOCK	Jammed	215.10 FL	*135.00 FL
13	1		*REAR BOOT WEATHERSTRIP	Torn	112.60 FL	*112.60 FL
14	1		*REAR BOOT LID SPORTS LOGO	Necessary	48.50 FL	*48.50 FL
15	1		*REAR BOOT LID SUZUKI EMBLEM	Necessary	66.75 FL	*66.75 FL
16	1		*REAR BOOT LID SX4 EMBLEM	Necessary	27.35 FL	*27.35 FL
17	1		*REAR END PANEL	Dented	434.85 FL	*216.75 FL
18	1		*REAR END PANEL TOP GARNISH	Broken	102.75 FL	*68.55 FL
19	1		*REAR SPARE WHEEL PANEL	Not Damaged	565.90 FL	*- FL
20	1		*REAR EXHAUST SILENCER BOX ASSY	Repair	634.70 FL	*- FL
21	1		*REVERSE CAMERA	Not Damaged	300.00 FS	*- FS
22	1		*REVERSE SENSOR	Scratched	280.00 FS	*200.00 FS
23	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
24	1		*END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,860.20	3,614.50
- List Item Discount on L Items 15.00/15.00% (\$)	1,080.78	503.18
Total Parts (\$)	6,779.42	3,111.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REARRANGE ELECTRICAL WIRINGS CHECK LIGHTINGS	New	80.00	0.00
2	TO REMOVE AND RELACE UPHOLSTERY TRIM GARNISHES TO FACILITATE REPAIR	New	100.00	0.00
3	TO REMOVE ,REPAIR AND REPLACE DAMAGE BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
4	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	1,000.00	600.00
5	TO REMOVE AND RENEW REVERSE SENSOR	New	150.00	60.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	0.00
7	TO REMOVE,REPLACE EXHAUST SILENCER BOX & RE-ALIGN	New	120.00	0.00
Gross Labour Cost (\$\$)			2,750.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >