

SJX9033B. 2010 July.

TP China.

BMW 523i 2497cc

Denise.

WBAFP32060CS43949.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rear Number Plate

HP

30(SN) X

Rear Number Plate Holder

New

30(SN) X

Rear Bumper Deformed

1530 /

Rear Bumper Clips. New

50(SN) /

Rear Bumper Side Holder x02

HP New

99.X2=198 X

Rear Bumper Reflector x02

LH cruld

~~69~~ X2 = ~~138~~ 69.

Rear Bumper Undercover

cracked 168 /

Rear Bumper Undercover Clips.

New

20(SN) /

Rear Bumper Centre Guide

cruld

195 /

Rear Bumper Reinforcement

dented

697 /

Rear Bumper Kick Sensor

HP New

320 X

Rear Bumper Kick Sensor Cover

cruld

282 /

Reverse Sensor x 04.

2 pieces damaged

~~260 X 4 = 1040~~

520

SJX9033B.

Rear End Panel.	Repair	921	+
Rear End Panel Top Garnish?	NY	198	+
Rear End Panel Sealant.	Per	60(SN)	+
Taillamp x 02	LH cranked	654 x 2 =	1308 654
Taillamp Side Cover x 02	LH cranked	39 x 2 =	78 39
Bootlid	Dented	1615	✓
Bootlid Lock	Dented	211	✓
Bootlid Weatherstripe.	NY	288.	+
Bootlid Reflector x 02	RH cranked	392 x 2 =	784 392
BMW Logo	✓ New	98	✓
523i Emblem.	✓ New	75	✓
Rear Exhaust Pipe.	✓ New	1651	X
Rear Exhaust Mounting.	✓ New	38	X

6545 S.N: 70

589050

SJX 9033B

Panel Beating.	1200 600
Spray Painting.	1000 600
Wiring.	100 30
To spray tuft coat	155 50
To remove reverse sensor	100 60
To remove upholstery.	150 40
To transfer bootlid fittings.	150 80
To remove exhaust pipe	150 X
To perform diagnostic test.	200. X
	1460

Total: 7420.50

2/s: 5.9K

05 Days.