

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITA	L INSURANCE LTD	Ī	Ref:	CS3/FCI21012330/R1qf3e2	
	36 ROBINSON RO #16-01 CITY HOUS	ROAD DUSESINGAPORE 068877		Date:	10/12/2021	
			(	Code:	FCI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBE 7851P	Veh. Inspected		SMM 9915D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D21003382MFCV	Excess (\$)		0.00	
	Assign From	JOANNE TAN JO ANN	Assign Date		06/12/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA ALTIS 1.6L	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MR053REH104543949	Colour		GREY	
	Odometer	95591 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	тоуо		6 mm	
	L/H Front Tyre	205/55 R16	тоуо		6 mm	
	R/H Rear Tyre	205/55 R16	тоуо		6 mm	
	L/H Rear Tyre	205/55 R16	тоуо		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	LE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
5.	General Information					
	Accident Date	04/12/2021	Inspect Date / T	ime	07/12/2021 ( 01:54 PM )	
	Survey held at	D MOTORWERKZ PTE LTD				
		280 WOODLANDS INDUSTRIAL PARK E5 #01-03 SINGAPORE 757322				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$50,000.00					

Report Ref No. CS3/FCI21012330/R1qf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser