

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21012334/KQF3E2**Date:** 11/05/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001864869
Claimant Vehicle No :	SLL2695B	Insured Vehicle No :	SMS8221Y
Date of Loss:	04/12/2021	Nature of Claim:	TP
		Claim No:	266420

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL2695B	Engine No:	PE10404277
Make & Model:	MAZDA 5, 2.0 SP.6EAT SUNROOF (A)	Chassis No:	JM6CW1071G0124782
Reg. Date:	20/02/2017 (Man. Year: 2016)	Odometer:	75125 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,135.04	2,923.04	212.00	6.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	1,080.00	400.00	27.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,615.04	4,003.04	612.00	13.26
+ GST 8.00/8.00% (S\$)	369.20	320.24	48.96	13.26
Nett Amount (S\$)	4,984.24	4,323.28	660.96	13.26

INSPECTION

Date of Assignment:	06/12/2021		
Date Inspected:	06/12/2021	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 08 May 2023)	
Parts:	N/A	MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL2695B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	981.00 FL	*981.00 FL
2	6		*REAR BUMPER CLIPS	Necessary	35.40 FL	*35.40 FL
3	1		*REAR TAILGATE	Bent	1,637.00 FL	*1,637.00 FL
4	1		*TAILGATE EMBLEM (5)	Necessary	38.00 FL	*38.00 FL
5	1		*TAILGATE EMBLEM (MAZDA)	Necessary	38.60 FL	*38.60 FL
6	1		*TAILGATE EMBLEM (SKYACTIV)	Necessary	53.30 FL	*53.30 FL
7	1		*TAILGATE INNER LOCK	Repair	265.00 FL	*- FL
8	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
9	1		*REAR BUMPER BODY PROTECTOR	Necessary	90.00 FS	*90.00 FS
10	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
11	1		*TAILGATE OUTER GARNISH	Mtg Cracked	458.00 FL	*458.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,836.30	3,571.30
- List Item Discount on L Items 20.00/20.00% (\$)	701.26	648.26
Total Parts (\$)	3,135.04	2,923.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR TOP SPOILER, LOCK ASSY, REFLECTORS, TO KNOCK & REPAIR REAR END PANEL AND REALIGN THE SAME	New	600.00	450.00
3	PUTTY & RESPRAY ON REAR END PANEL, TAILGATE, REAR BUMPER	New	700.00	450.00
4	REMOVE & REFIX REVERSE CAMERA AND RESET SYSTEM	New	30.00	30.00
5	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (S\$)			1,480.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >