

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012337/UTY3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00126242000
Claimant Vehicle No : SMX4583C **Insured Vehicle No :** GBH9396H
 Date of Loss: 02/12/2021 Nature of Claim: TP Claim No: SNM21D207023/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX4583C**
 Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B5672852
 Reg. Date: 14/01/2021 (Man. Year: 2020) Chassis No: JHMRU1810JX202844
 Colour: White Odometer: 20471 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,055.66	2,107.01	948.65	31.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,460.00	7,120.00	3,340.00	31.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,515.66	9,227.01	4,288.65	31.73
+ GST 7.00/7.00% (S\$)	946.10	645.89	300.21	31.73
Nett Amount (S\$)	14,461.76	9,872.90	4,588.86	31.73

INSPECTION

Date of Assignment: 06/12/2021
 Date Inspected: 14/01/2022 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
 15 Ubi Road 4
 Singapore 408610
 Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2022)
Parts: M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMX4583C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SET,L.RR.OUTSIDE	Badly Dented	491.40 FS	*491.40 FS
2	1		*PANEL COMP,L.RR.DOOR	Badly Dented	701.32 FS	*701.32 FS
3	1		*TAPEL,RR.DOOR SASH	Necessary	15.75 FS	*15.75 FS
4	1		*TAPEL,RR.DOOR PROTECTION	Necessary	19.27 FS	*19.27 FS
5	1		*SUB SEALL .RR.DOOR RR	Not Necessary	6.52 FS	*- FS
6	1		*SEALL.DOOR LOWER	Not Necessary	4.42 FS	*- FS
7	1		*SUB SEALL.RR.DOOR CENTER	Cut	35.10 FS	*35.10 FS
8	1		*LATCH ASSYL.RR.DOOR	Not Necessary	159.67 FS	*- FS
9	1		*CAPL .CHILD LOCK	Not Necessary	2.92 FS	*- FS
10	1		*WEATHERSTRIPL.RR.DOOR OUTER	Not Necessary	17.25 FS	*- FS
11	1		*MOLDING ASSYL.RR.DOOR	Not Necessary	35.85 FS	*- FS
12	1		*MOLDING ASSYL.FR.DOOR	Not Necessary	20.25 FS	*- FS
13	1		*GARNISH ASSY ,L.SIDE	Repair	301.95 FS	*- FS
14	1		*PROTECTION TAPE,L,SILL	Necessary	16.57 FS	*16.57 FS
15	1		*PROTECTOR,L.RR.WHEEL ARCH	Distorted	140.40 FS	*140.40 FS
16	1		*FENDERL.RR.INNER	Not Necessary	73.80 FS	*- FS
17	4		*CLIPINNER FENDER	Not Necessary	1.20 FS	*- FS
18	1		*REGULATOR ASSYL.RR.DOOR	Not Necessary	294.82 FS	*- FS
19	1		*DISK,ALUMINIUM WHEEL	Cut	624.75 FS	*624.75 FS
20	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
21	1		*CAP ASSYALUMINIUM WHEEL CTR	Cut	42.45 FS	*42.45 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,055.66	2,107.01
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	180.00	180.00
2	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00
3	BODY JOINT SEALANT	New	100.00	100.00
4	BODY UNDERSIDE COATING	New	100.00	100.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	250.00
6	REMOVE & INSTALL SENSORS	New	200.00	160.00
7	REMOVE & TRANSFER ITEMS TO NEW RR L DR ADJUST	New	650.00	450.00
8	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	350.00
9	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
10	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	450.00	350.00
11	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	450.00	0.00
12	CUT & RENEW RR L FENDER STRAIGHTEN INNER PANEL	New	4,200.00	2,600.00
13	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,800.00	2,080.00
Gross Labour Cost (\$)			10,460.00	7,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >