

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012339/EQF3N2**Date:** 28/01/2022**REFERENCE**

Insured/Claimant:	TAY NGAK MONG	Policy No:	1800144741	
Date of Loss:	04/12/2021	Nature of Claim:	OD	Claim No: 8974278496SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG1536Z		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UHK0272
Reg. Date:	06/12/2018 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH004307
Colour:	White	Odometer:	63846 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,691.65	7,765.37	926.28	10.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,040.00	4,685.00	2,355.00	33.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,731.65	12,450.37	3,281.28	20.86
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	15,431.65	12,150.37	3,281.28	21.26
+ GST 7.00/7.00% (S\$)	1,080.22	850.53	229.69	21.26
Nett Amount (S\$)	16,511.87	13,000.90	3,510.97	21.26

INSPECTION

Date of Assignment:	06/12/2021	
Date Inspected:	07/12/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,LH	Broken	663.00 FL	*663.00 FL
2	1		*HEADLAMP ASSY,RH	Broken	663.00 FL	*663.00 FL
3	1		*TANK,WINDSHIELD WASHER	Crushed	75.00 FL	*75.00 FL
4	1		*HORN	Not Necessary	79.00 FL	*- FL
5	1		*CONDENSER ASSY,A/C REFRIGE	Bent	762.00 FL	*762.00 FL
6	1		*RADIATOR ASSY	Bent	972.00 FL	*972.00 FL
7	1		*PANEL,AIR GUIDE	Broken	112.00 FL	*112.00 FL
8	1		*SHROUD,COOLING FAN	Broken	131.00 FL	*131.00 FL
9	1		*FAN,COOLING,LH	Not Necessary	77.00 FL	*- FL
10	1		*TANK ASSY,RADIATOR COND	Not Necessary	42.00 FL	*- FL
11	1		*MOTOR,COOLING FAN	Not Necessary	484.00 FL	*- FL
12	1		*DUCT,A/CLNR INTAKE	Broken	131.00 FL	*131.00 FL
13	1		*FACE,FR BUMPER	Broken	706.00 FL	*706.00 FL
14	1		*GRILLE,RADIATOR	Broken	557.00 FL	*557.00 FL
15	1		*AIR DAM,SIDE,FR RH	Not Necessary	18.00 FL	*- FL
16	1		*AIR DAM,SIDE,FR LH	Not Necessary	18.00 FL	*- FL
17	1		*GRILLE,FR UNDER	Broken	165.00 FL	*165.00 FL
18	1		*BRACKET,FR BUMPER,RH	Broken	13.00 FL	*13.00 FL
19	1		*BRACKET,FR BUMPER,LH	Broken	13.00 FL	*13.00 FL
20	1		*COVER,HEADLAMP SUPT PANEL	Broken	62.00 FL	*62.00 FL
21	1		*MARK,THREE-DIA	Necessary	70.00 FL	*70.00 FL
22	1		*HOOD	Dented	737.00 FL	*737.00 FL
23	1		*INSULATOR,HOOD	Crushed	177.00 FL	*177.00 FL
24	1		*HINGE,HOOD,LH	Bent	56.00 FL	*56.00 FL
25	1		*HINGE,HOOD,RH	Bent	56.00 FL	*56.00 FL
26	1		*DAM,HOOD	Not Necessary	20.00 FL	*- FL
27	1		*WEATHERSTRIP,HOOD,RR	Not Necessary	51.00 FL	*- FL
28	1		*FENDER,FR RH	Dented	500.00 FL	*500.00 FL
29	1		*PANEL ASSY,FR END	Dented	1,055.00 FL	*1,055.00 FL
30	1		*PANEL,HEADLAMP SUPPORT,UPR	Dented	66.00 FL	*66.00 FL
31	1		*COVER,ENG ROOM UNDER,FR	Not Necessary	99.00 FL	*- FL
32	1		*SHIELD,FR WHEELHOUSE,RH	Not Necessary	98.00 FL	*- FL
33	1		*COVER,FR DECK,RH	Broken	16.00 FL	*16.00 FL
34	1		*GARNISH,FR DECK	Not Necessary	178.00 FL	*- FL
35	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
36	2		*EMBLEM ECO	Necessary	34.00 FS	*34.00 FS
37	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
38	1		*PANEL AIR GUIDE,LH (Supplementary)	Broken	11.00 FL	*11.00 FL
39	1		*PANEL AIR GUIDE,RH (Supplementary)	Broken	11.00 FL	*11.00 FL
40	10		*CLIPS (Supplementary)	Necessary	40.00 FL	*40.00 FL
41	6		*CLIPS (Supplementary)	Necessary	18.00 FL	*18.00 FL
42	1		*COVER,FR BUMPER (Supplementary)	Missing	13.00 FL	*13.00 FL
43	1		*GARNISH,FR PILLAR,RH (Supplementary)	Broken	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,772.00	9,578.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,080.35	1,812.63
Total Parts (\$\$)	8,691.65	7,765.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,BONNET,SUPPORT,FRT RH FENDER & AFFECTED AREA.REPAIR ON FRT LH FENDER & FRT BOTH BODY CHASSIS	New	3,600.00	2,025.00
2	PAINT WORK ON FRT BUMPER,BONNET,SUPPORT,BOTH FRT BODY CHASSIS,BOTH FRT FENDER & BODY KIT	New	2,800.00	2,100.00
3	REMOVE & REPLACE RADIATOR,CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	REMOVE & INSTALL BODY KIT FOR FACILITATE REPAIR	New	80.00	80.00
6	PERFORM RUST PREVENTION	New	80.00	40.00
7	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
8	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM (Supplementary)	New	30.00	30.00
10	CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE (Supplementary)	New	120.00	120.00
Gross Labour Cost (\$\$)			7,040.00	4,685.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >