

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012340/KVY3N2**Date:** 15/12/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00080272104

Claimant Vehicle No : SJT6248P **Insured Vehicle No :** SLN2723T

Date of Loss: 03/12/2021 Nature of Claim: TP Claim No: SNM21D207024/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT6248P**

Make & Model: TOYOTA SIENTA, 1.5 X LIMITED (A) Engine No: 1NZC923507

Reg. Date: 18/02/2009 (Man. Year: 2008) Chassis No: NCP815051868

Colour: Metallic Silver Odometer: 214289 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50R16 Rear Tyre Size: 205/50R16

Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,823.00	4,649.60	8,173.40	63.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	2,160.00	1,410.00	39.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,393.00	6,809.60	9,583.40	58.46
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	16,393.00	5,400.00	10,993.00	67.06

INSPECTION

Date of Assignment: 07/12/2021

Date Inspected: 07/12/2021 Inspected At: Poon Siang Seow (HQ)
160 Sin Ming Drive, #05-13 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2021)
Parts: M1-MPV	TOYOTA SIENTA 1.5 X LIMITED (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT6248P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL BOOT COVER	Bent	1,177.80 F	*1,177.80 FL
2	2		*TAIL BOOT DAMPER	Serviceable	380.80 F	*- FL
3	1		*TAIL BOOT W/S GLASS MOULDING	Necessary	211.80 F	*211.80 FL
4	1		*TAIL BOOT INNER BOARD	Mtg Cracked	580.80 F	*481.90 FL
5	1		*TAIL BOOT INNER LOCK	Dented	458.80 F	*381.90 FL
6	1		*TAIL BOOT WIPER MOTOR	Distorted/Jammed	560.80 F	*560.80 FL
7	1		*TAIL BOOT WIPER ARM AND BLADE	Serviceable	128.80 F	*- FL
8	1		*TAIL BOOT OUTER HANDLE	Serviceable	118.80 F	*- FL
9	2		*TAIL BOOT NUMBER PLATE LAMP	Serviceable	120.80 F	*- FL
10	1		*TAIL BOOT COVER	Mtg Cracked	589.80 F	*470.70 FL
11	1		*TAIL BOOT LOGO	Necessary	81.70 F	*81.70 FL
12	1		*TAIL BOOT COVER BADGE SIENTA	Necessary	69.70 F	*69.70 FL
13	1		*TAIL GATE REVERSE CAMERA	Shorted	250.00 F	*250.00 FL
14	1		*REAR PANEL	Bent	301.30 F	*301.30 FL
15	1		*REAR PANEL TOP GARNISH	Cracked	211.80 F	*211.80 FL
16	1		*REAR SPARE TYRE BOARD COVER	Buckled	580.00 F	*580.00 FL
17	1		*REAR SPARE TYRE PANEL	Repair	880.80 F	*- FL
18	2		*REAR FENDER INNER GARNISH	Serviceable	901.80 F	*- FL
19	1		*REAR FENDER RIGHT	Repair	990.80 F	*- FL
20	1		*REAR FENDER TOP FENDER PANEL	Repair	456.80 F	*- FL
21	1		*REAR BUMPER	Bent	766.20 F	*766.20 FL
22	1		*REAR BUMPER TOWING COVER	Missing	45.00 F	*45.00 FL
23	2		*REAR BUMPER RETAINER	Distorted	150.80 F	*150.80 FL
24	2		*REAR BUMPER REFLECTOR	Serviceable	60.00 F	*- FL
25	2		*TAIL LAMP	Serviceable	1,005.60 F	*- FL
26	1		*REAR EXHAUST BOX	Repair	950.00 F	*- FL
27	1		*TAIL BOOT RUBBER (\$287.10)(50%)	Distorted	361.70 FS	*143.55 FS
28	1		*REAR BUMPER SENSOR	Dented	350.00 FS	*200.00 FS
29	1		*NUMBER PLATE	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,823.00	6,084.95
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,435.35
Total Parts (\$)	12,823.00	4,649.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	100.00	60.00
2	TO REMOVE AND REFIT W/S GLASS AND CUSHION	New	350.00	180.00
3	WIRING	New	120.00	20.00
4	PANEL BEATING	New	1,800.00	900.00
5	SPRAY PAINTING	New	1,200.00	1,000.00
			Gross Labour Cost (\$)	3,570.00
				2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >