

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012349/ETF3E2**Date:** 03/01/2022**REFERENCE**

Insured/Claimant: HOE SIN KONG PAUL (HE XINGGUANG)
Date of Loss: 05/12/2021

Policy No: 1900111250
Nature of Claim: OD Claim No: 4868904182SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ8783M**
Make & Model: MITSUBISHI ECLIPSE CROSS, 1.5 (A) Engine No: 4B40GB4565
Reg. Date: 21/06/2019 (Man. Year: 2018) Chassis No: JMAXTGK1WJZ004746
Colour: Red Odometer: 33708 km
Engine Capacity: 1499 cc
Market Value/New Car Price: S\$94,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,352.25	4,103.31	1,248.94	23.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,010.00	3,235.00	2,775.00	46.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,362.25	7,338.31	4,023.94	35.41
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	10,962.25	6,938.31	4,023.94	36.71
+ GST 7.00/7.00% (S\$)	767.36	485.68	281.68	36.71
Nett Amount (S\$)	11,729.61	7,423.99	4,305.62	36.71

INSPECTION

Date of Assignment: 07/12/2021

Date Inspected: 06/12/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY, RH	Broken	1,986.00 FL	*1,986.00 FL
3	1		*FACE, FR BUMPER	Broken	718.00 FL	*718.00 FL
4	1		*COVER, FR BUMPER	Broken	382.00 FL	*382.00 FL
5	1		*EXTENSION, FR BUMPER	Cut	318.00 FL	*318.00 FL
6	1		*BRKT, F/BMPR T/SIG LAMP, RH	Not Necessary	17.00 FL	*- FL
7	1		*GARNISH, FR BUMPER SIDE	Broken	214.00 FL	*214.00 FL
8	1		*GARNISH, FR BUMPER SIDE	Not Necessary	77.00 FL	*- FL
9	1		*BAR, FR BUMPER GUARD	Not Necessary	100.00 FL	*- FL
10	1		*REINFORCEMENT, FR BUMPER	Not Necessary	555.00 FL	*- FL
11	1		*REINF, FR BUMPER SIDE, RH	Bent	35.00 FL	*35.00 FL
12	1		*REINFORCEMENT, FR BUMPER	Bent	236.00 FL	*236.00 FL
13	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 FL	*- FL
14	2		*STAY, FR BUMPER	Not Necessary	18.00 FL	*- FL
15	1		*COVER, HEADLAMP WASHER HOLE	Missing	53.00 FL	*53.00 FL
16	1		*ACTUATOR, HEADLAMP WASHER, R	Broken	113.00 FL	*113.00 FL
17	1		*HOSE ASSY, HEADLAMP WASHER	Not Necessary	185.00 FL	*- FL
18	1		*FENDER, FR RH	Dented	541.00 FL	*541.00 FL
19	1		*MOULDING, FR WHEEL ARCH, RH	Not Necessary	151.00 FL	*- FL
20	1		*GRILLE ASSY, RADIATOR	Cracked	486.00 FL	*486.00 FL
21	1		*COVER, FR BUMPER GRILLE	Not Necessary	302.00 FL	*- FL
22	1		*PANEL, AIR GUIDE	Not Necessary	32.00 FL	*- FL
23	1		*PANEL, AIR GUIDE SIDE, RH	Not Necessary	82.00 FL	*- FL
24	1		*PNL, HEADLAMP SUPT, UPR RH	Not Necessary	59.00 FL	*- FL
25	1		*PANEL, HEADLAMP SUPPORT, UPR	Bent	172.00 FL	*172.00 FL
26	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
27	1		*REINF, FR BUMPER SIDE, LH (Supplementary)	Bent	35.00 FL	*35.00 FL
28	1		*GROMMET (Supplementary)	Necessary	4.00 FL	*4.00 FL
29	1		*CLIPS (X5) (Supplementary)	Necessary	10.00 FL	*10.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,945.00	5,323.00
- List Item Discount on L Items 23.00/23.00% (\$)	1,592.75	1,219.69
Total Parts (\$)	5,352.25	4,103.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER, RHF FENDER & FR SUPPORT PNL. REPAIR BONNET & RHF DOOR	New	2,250.00	675.00
2	RESPRAY FR BUMPER, RHF FENDER, FR SUPPORT PNL BONNET & RHF DOOR	New	2,400.00	1,400.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	0.00
4	TOP UP AC GAS	New	80.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	SUPPLY FRT NUMBER PLATE WITH CASING	New	50.00	50.00
8	REMOVE & REFIT FR PARKING SENSOR	New	80.00	80.00
9	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
10	SUPPLY BODY PNL SEALANT	New	60.00	40.00
11	SPRAY FRONT RE-INFORCEMENT & FRONT SUPPORT UPPER PANEL (Supplementary)	New	350.00	350.00
12	REPLACE FRONT RE-INFORCEMENT & FRONT SUPPORT UPPER PANEL (Supplementary)	New	450.00	450.00
Gross Labour Cost (\$\$)			6,010.00	3,235.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >