

File No: Steve

Ref: CS/AIG21012349/ETF3E2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. 1900111250

Claims No. 4868904182SG

Sum Insured: _____ Excess: 400

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs. _____ days Res.: Yes or No

Lum Sum: _____ % J-Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJA8783M

Yr Regn: 2/6/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Mitsubishi Eclipse c.c. 1499

Colour: Red NC: Insured / Std / NI / HA

Sp. Reading: 33708 T/Radio: Insured / Std / NI / HA

Eng/No: _____

C/No: JMAXIGKJWJZ004746

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 225/55R18

R: 13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / XOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 5/12/21

D.O.A. 6/12/21

Survey held at Cycle & Carriage

Des. of Damagos: Frt Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-94K

Confirm final figure at \$7338.31, 5days before GST and excess \$400

RED:4023.94;35%

Date/Time, File Pass to?

☐ : Prelim. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Funka

Other

Total

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invt (\$

☐ : V&A and (\$

Request Form:

Letter 2146 / 1.0.1: 12



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11519/HOE SIN KONG PAUL (HE XINGGUANG) Reg No/Reg Date SJQ8783M / 21/06/201 Date In/Mileage / 0 Chassis No JMAXTGK1WJZ004746 Engine No 4B40GB4565 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	06/12/2021/ 14:00	TLE	261 / Edwin Caina	18286		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000		RENEW FR BUMPER , RHF FENDER & FR SUPPORT PNL REPAIR BONNET & RHF DOOR	1 1/2 x 450				675 2250.00
E PNT98000		RSPRAY FR BUMPER , RHF FENDER , FR SUPPORT PNL BONNET & RHF DOOR	4 x 350				1400 2400.00
E PNT88000		REMOVE & REFIT AC COND & RADIATOR					100.00
M SUNDRY		TOP UP AC GAS					80.00
A 54900099		CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM					30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00
M SUNDRY		SUPPLY FR NUMBER PLATE WITH CASING					50.00
E PNT88000		REMOVE & REFIT FR PARKING SENSOR					80.00
M SUNDRY		APPLY ANTI CORROSION ON AFFECTED AREAS					40.00
M SUNDRY		SUPPLY BODY PNL SEALANT					40 60.00
M SUNDRY		Sundries					20.00
M HEADLAMP ASSY, RH	BR		1.00	1986.00	23.00		1529.22
M FACE, FR BUMPER	BR		1.00	718.00	23.00		552.86
M COVER, FR BUMPER	BR (Black)		1.00	382.00	23.00		294.14
M EXTENSION, FR BUMPER	cut (Silver)		1.00	318.00	23.00		244.86
M BRKT, F/BMPR T/SIG LAMP, RH	?		1.00	17.00	23.00		13.09
M GARNISH, FR BUMPER SIDE	BR (RH chrome)		1.00	214.00	23.00		164.78
M GARNISH, FR BUMPER SIDE	?		1.00	77.00	23.00		59.29
M BAR, FR BUMPER GUARD	?		1.00	100.00	23.00		77.00
M REINFORCEMENT, FR BUMPER	?		1.00	555.00	23.00		427.35

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11519/HOE SIN KONG PAUL (HE XINGGUANG) Reg No/Reg Date SJQ8783M / 21/06/201 Date In/Mileage / 0 Chassis No JMAXTGK1WJZ004746 Engine No 4B40GB4565 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS SU Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	06/12/2021/ 14:00	TLE	261 / Edwin Caina	18286		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	REINF,FR BUMPER SIDE,RH			1.00	35.00	23.00	26.95
M	REINFORCEMENT,FR BUMPER			1.00	236.00	23.00	181.72
M	BRACKET,FR BUMPER SIDE,RH			1.00	18.00	23.00	13.86
M	STAY,FR BUMPER			2.00	9.00	23.00	13.86
M	COVER,HEADLAMP WASHER HOLE			1.00	53.00	23.00	40.81
M	ACTUATOR,HEADLAMP WASHER,R			1.00	113.00	23.00	87.01
M	HOSE ASSY,HEADLAMP WASHER			1.00	185.00	23.00	142.45
M	FENDER,FR RH			1.00	541.00	23.00	416.57
M	MOULDING,FR WHEEL ARCH,RH			1.00	151.00	23.00	116.27
M	GRILLE ASSY,RADIATOR			1.00	486.00	23.00	374.22
M	COVER,FR BUMPER GRILLE			1.00	302.00	23.00	232.54
M	PANEL,AIR GUIDE			1.00	32.00	23.00	24.64
M	PANEL,AIR GUIDE SIDE,RH			1.00	82.00	23.00	63.14
M	PNL,HEADLAMP SUPT,UPR RH			1.00	59.00	23.00	45.43
M	PANEL,HEADLAMP SUPPORT,UPR			1.00	172.00	23.00	132.44
M	LLC 4L			1.00	26.00	23.00	20.02

SURVEYOR NAME: Steve (LKK)SURVEYOR SIGNATURE: 6/12/21, 2.30pmDATE: 06-12-21REMARKS: Excess - 1P/P
by Ref sy
5 days

Confirm & accepted by

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on **10,524.52** **736.72**

Total Payable 11,261.24

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.