

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012352/AEA3Q2**Date:** 16/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070036434
Claimant Vehicle No :	SNA3151G	Insured Vehicle No :	SFW221L
Date of Loss:	29/11/2021	Nature of Claim:	TP
		Claim No:	9038048595SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA3151G	Engine No:	M15AY111436
Make & Model:	TOYOTA YARIS CROSS, 1.5 X B-PKG CVT (A)	Chassis No:	MXPB103004985
Reg. Date:	16/06/2021 (Man. Year: 2021)	Odometer:	15380 km
Colour:	Red		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,350.97	9,733.35	4,617.62	32.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	2,080.00	1,090.00	34.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,520.97	11,813.35	5,707.62	32.58
Approved Total (Overridden) (S\$)		9,450.00		
(S\$)	17,520.97	9,450.00	8,070.97	46.06
+ GST 7.00/7.00% (S\$)	1,226.47	661.50	564.97	46.06
Nett Amount (S\$)	18,747.44	10,111.50	8,635.94	46.06
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,818.95		
Global Sum Settlement (S\$)		10,810.00		

INSPECTION

Date of Assignment:	03/12/2021	MG Solution Pte Ltd (HQ)
Date Inspected:	03/12/2021 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WIPER GARNISH	Cut	420.20 FL	*420.20 FL
2	1		*BONNET	Dented	1,255.30 FL	*1,050.00 FL
3	2		*BONNET HINGES	Bent	124.60 FL	*124.60 FL
4	1		*BONNET LOCK	Damaged	230.50 FL	*168.00 FL
5	1		*FRONT BUMPER	Deformed	980.20 FL	*750.00 FL
6	1		*FRONT BUMPER LOWER LID	Cut	650.30 FL	*510.00 FL
7	2		*FRONT BUMPER SIDE RETAINER	Necessary	124.80 FL	*124.80 FL
8	1		*FRONT BUMPER TOWING COVER	Deformed	122.50 FL	*45.00 FL
9	1		*FRONT BUMPER TOP RUBBER SEAL	Torn	90.00 FL	*90.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	420.00 FL	*370.00 FL
11	1		*FRONT BUMPER REINFORCEMENT BRACKET	Bent	166.20 FL	*166.20 FL
12	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	180.00 FL	*180.00 FL
13	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	108.20 FL	*- FL
14	1		*FRONT BUMPER UNDER COVER	Deformed	411.20 FL	*285.00 FL
15	1		*TOP INNER GRILLE	Cracked	388.50 FL	*388.50 FL
16	1		*FRONT GRILLE	Cracked	510.20 FL	*510.20 FL
17	1		*FRONT GRILLE COVER	Not Necessary	160.20 FL	*- FL
18	1		*FRONT GRILLE LOGO	Necessary	90.00 FL	*90.00 FL
19	2		*FRONT FENDER	Buckled	1,160.60 FL	*1,160.60 FL
20	1		*FRONT FENDER INNER COWLING	O/S Torn	380.40 FL	*190.20 FL
21	2		*FRONT FENDER PROTECTOR	Cracked	840.40 FL	*560.00 FL
22	1		*FRONT DAY LIGHT	O/S Cracked	1,160.40 FL	*580.20 FL
23	1		*FRONT DAY LIGHT HOUSING	O/S Cracked	310.60 FL	*155.30 FL
24	2		*HEADLAMP	Cracked	3,710.60 FL	*3,000.00 FL
25	2		*HEADLAMP LOWER SUPPORT PANEL	Bent	460.40 FL	*460.40 FL
26	1		*FRONT SUPPORT PANEL	Cracked	720.00 FL	*720.00 FL
27	1		*FRONT SUPPORT PANEL COVER	Deformed	133.20 FL	*133.20 FL
28	1		*RADIATOR	Not Necessary	1,255.30 FL	*- FL
29	1		*AIR CONDENSOR	Not Necessary	1,055.20 FL	*- FL
30	2		*AIR CONDENSOR SIDE GUIDE	Not Necessary	230.40 FL	*- FL
31	1		*WASHER TANK	Torn	320.50 FL	*155.00 FL
32	1		*AIR DUCT	Cracked	210.40 FL	*210.40 FL
33	2		*AIR DUCT BRACKET	Bent	180.00 FL	*180.00 FL
34	1		*FRONT NUMBER PLATE	Cut	50.00 FS	*50.00 FS
35	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
36	1		*SET FRONT GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
37	1		*SET FRONT FENDER COWLING CLIPS	Necessary	20.00 FS	*20.00 FS
38	1		*SET FRONT FENDER PROTECTOR CLIPS	Necessary	20.00 FS	*20.00 FS
39	1		*SET SUPPORT PANEL COVER CLIP	Necessary	20.00 FS	*20.00 FS
40	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
41	1		*HORN	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,991.30	12,927.80
- List Item Discount on L Items 25.00/25.00% (S\$)	4,640.33	3,194.45
Total Parts (S\$)	14,350.97	9,733.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVING AND RPELACING PARTS	New	1,400.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	1,050.00
3	WIRING CHECK	New	150.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			3,170.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >