

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC21012354/Vtf3e2	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	15/12/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 952S	Veh. Inspected		SKF 821K	
	Policy No.	Z/21/VC06/111964	Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		07/12/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA COROLLA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MR053REH104557651	Colour		WHITE	
	Odometer	102833 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45ZR17	MICHELIN		6 mm	
	L/H Front Tyre	215/45ZR17	MICHELIN		6 mm	
	R/H Rear Tyre	215/45ZR17	MICHELIN		6 mm	
	L/H Rear Tyre	215/45ZR17	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S FRONT PORTION.				
5.	General Information					
	Accident Date	30/11/2021	Inspect Date /	Time	07/12/2021 (02:00 PM)	
	Survey held at	GFORCE AUTOTECH PTD LTD				
		10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE SINGAPORE 417868				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21012354/Vtf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser