

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012355/AEA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070158537
Claimant Vehicle No :	SLD508P	Insured Vehicle No :	SDR1721D
Date of Loss:	30/11/2021	Nature of Claim:	TP
		Claim No:	2076819924SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD508P	Engine No:	P520357070
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Chassis No:	JM6BM42A8G0337894
Reg. Date:	31/05/2016 (Man. Year: 2016)	Odometer:	60132 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,718.40	1,693.36	3,025.04	64.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	950.00	1,100.00	53.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,768.40	2,643.36	4,125.04	60.95
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	6,768.40	2,100.00	4,668.40	68.97
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		2,340.00		

INSPECTION

Date of Assignment:	06/12/2021		
Date Inspected:	06/12/2021	Inspected At:	Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,047.80 F	*1,047.80 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	76.00 F	*- FL
4	1		*REAR BUMPER TOW COVER	O/S Missing	67.40 F	*33.70 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	109.80 F	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	537.30 F	*537.30 FL
7	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
8	1		*REAR END PANEL	Repair	469.70 F	*- FL
9	1		*REAR END PANEL TOP GARNISH	Cracked	210.40 F	*210.40 FL
10	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
11	2		*TAILLAMP	Not Necessary	1,830.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,718.40	2,059.20
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	365.84
Total Parts (\$\$)	4,718.40	1,693.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	30.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	40.00
			Gross Labour Cost (\$)	2,050.00
				950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >