

TPA 6  
Ashes.

SLD508P 2016 May.  
Mazda 3 1496cc  
JM6BM42A860337894

Rear Bumper	Damaged	1047.80 ✓
Rear Bumper Lips	new	30(SN) ✓
Rear Bumper Side Holder x 02	NY m	38x2 = 76. X 33.70
Rear Bumper Tow Cover x 02	RA Missing	33.7x2 = 67.40
Rear Bumper Reflector x 02	NY HR	54.9x2 = 109.80 X
Rear Bumper Reinforcement.	Dented	537.30 X
Reverse Sensor	Damaged	<del>280(SN)</del> 200(SN)
Rear End Panel	Reps	469.70 X
Rear End Panel Top Garnish.	could	210.40 ✓
Rear End Panel Sealant.	NY HR	60(SN) X
Tail Lamp x 02	NY HR	915x2 = 1830. X

1829.20 SN = 230.  
146336

SLID 508 P.

Panel Beating

Spray Painting.

Wiring.

To spray tuff coat 950

To remove reverse sensor

To remove upholstery

~~800~~ 400

~~800~~ 400

~~50~~ 30

~~150~~ 30

~~100~~ 50

~~150~~ 40

total: 264336

L/S: 2.1K

03 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: