

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21012356/AEA3Q2**Date:** 10/06/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : GBH6121D **Insured Vehicle No :** GBK6344L

Date of Loss: 02/12/2021 Nature of Claim: TP Claim No: MFL2021D0005292

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH6121D**

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A) Engine No: YD25029281B

Reg. Date: 26/07/2018 (Man. Year: 2018) Chassis No: JN1MC2E26Z0030393

Colour: White Odometer: 124453 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: APLUS 6 mm Rear Left Side: APLUS 6 mm

Front Right Side: APLUS 6 mm Rear Right Side: APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,179.24	4,462.16	2,717.08	37.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	2,150.00	1,200.00	35.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,529.24	6,612.16	3,917.08	37.20
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	10,529.24	5,300.00	5,229.24	49.66
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,107.45		

INSPECTION

Date of Assignment: 06/12/2021

Date Inspected: 06/12/2021 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 May 2022)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH6121D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,998.40 FL	*1,998.40 FL
2	1		*TAILGATE UPPER LOCK	Damaged	287.10 FL	*287.10 FL
3	1		*TAILGATE LOWER LOCK	Not Necessary	203.10 FL	*- FL
4	2		*TAILGATE HINGE	Not Necessary	114.20 FL	*- FL
5	1		*TAILGATE WEATHER STRIP	Cut	198.90 FL	*198.90 FL
6	1		*TAILGATE 70KM STICKER	Necessary	27.00 FS	*15.00 FS
7	2		*TAILGATE SHOCK ABSORBER	Not Necessary	438.60 FL	*- FL
8	1		*TAILGATE HANDLE	Not Necessary	589.30 FL	*- FL
9	1		*REAR BUMPER	Deformed	660.60 FL	*660.60 FL
10	1		*REAR BUMPER STEP PANEL	Dented	285.90 FL	*285.90 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*40.00 FL
12	1		*REAR END PANEL	Dented	581.50 FL	*581.50 FL
13	1		*REAR NUMBER PLATE LAMP	Not Necessary	170.00 FL	*- FL
14	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	323.40 FS	*200.00 FS
15	1		*REAR CAMERA	Not Necessary	500.00 FS	*- FS
16	1		*BODY STICKER	Necessary	1,300.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,738.00	4,867.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	558.76	405.24
Total Parts (\$\$)	7,179.24	4,462.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
2	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
3	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
4	REMOVE & REFIX REAR CAMERA	New	100.00	50.00
5	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	900.00
6	RESPRAY PAINTING	New	1,000.00	900.00
7	TUFF KOTE	New	100.00	80.00
Gross Labour Cost (\$\$)			3,350.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >