



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200604

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 28/01/2022
Reference CC4/FCI21012359/Ega3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJH 3433D

Insured Veh. GBH 7574Z

Claim No. D21003375MFCV

Policy No.

Accident Date 03/12/2021

Inspection Date 07/12/2021

Description	Total
Survey Inspection	384.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	384.00
GST (7%)	26.88
Grand Total	410.88

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21012359/Ega3q2	
			Date: 28/01/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 7574Z		Veh. Inspected	SJH 3433D
Policy No.			Coverage (\$)	0.00
Claim No.	D21003375MFCV		Excess (\$)	0.00
Assign From	CHRIS		Assign Date	07/12/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH		c.c	1794
Engine No.	HIDDEN		Year of Reg.	2008
Chassis No.	JTDER12W803000572		Colour	GREY
Odometer	194890 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		195/65 R15	BRIDGESTONE	4 mm
L/H Front Tyre		195/65 R15	BRIDGESTONE	4 mm
R/H Rear Tyre		195/65 R15	BRIDGESTONE	4 mm
L/H Rear Tyre		195/65 R15	BRIDGESTONE	4 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2021		Inspection Date	07/12/2021
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 3433D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN GLASS	BROKEN	1,291.00	1,148.00
1	REAR WIPER MOTOR /LINKAGE	JAMMED	315.00	315.00
1	REAR WIPER BLADE	CUT	65.00	65.00
1	TAILGATE	DENTED	1,630.00	1,275.00
1	TAILGATE LOGO	NECESSARY	58.00	58.00
1	TAILGATE CHROME GARNISH	BROKEN	285.00	285.00
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	80.00	-
1	TAILGATE INNER TRIM UPPER LH	BROKEN	157.00	157.00
1	TAILGATE INNER TRIM UPPER RH	BROKEN	157.00	157.00
1	TAILGTAILGATE INNER TRIM LOWER	NOT NECESSARY	385.00	-
1	TAILGATE LOCK	BENT	539.00	470.00
1	TAILGATE RUBBER	TORN	369.00	274.00
1	TAILLAMP RH	NOT NECESSARY	287.00	-
1	REAR BUMPER	DENTED	627.00	564.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
2	REAR BUMPER SIDE RETAINER LH & RH @\$69.00	BROKEN	138.00	138.00
1	END PANEL TOP GARNISH	NOT NECESSARY	283.00	-
1	END PANEL	DENTED	590.00	590.00
1	REAR FENDER INNER TRIM LH	NOT NECESSARY	812.00	-
1	REAR FENDER INNER TRIM RH	NOT NECESSARY	812.00	-
1	SPARE TYRE PANEL (NPA)	NOT NECESSARY	-	-
	LESS 25% DISCOUNT		-2,232.50	-1,381.50
			6,697.50	4,144.50
	<u>SPECIAL NETT ITEMS</u>			
1	SEALANT (SN)	NECESSARY	40.00	40.00
1	TAILGATE EMBLEM -AEROTOURER (SN)	NECESSARY	20.00	20.00
1	REAR NUMBER PLATE (SN)	BROKEN	40.00	40.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	300.00	-
1	REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			620.00	300.00

Report Ref No. CC4/FCI21012359/Ega3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & RELACE REAR WINDSCREEN GLASS .		120.00	120.00
	TO INSTALL REVERSE CAMERA & DIAGNOSE FUNCTION.		80.00	30.00
	TO INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION .		80.00	30.00
	TO INSPECT REAR LIGHTING & CHECK WIRING.		50.00	30.00
	TO CUT OFF END PANEL TO REMOVE & REPLACE DAMAGED ITEMS ,REALIGN CONNECTION .		700.00	600.00
	TO REMOVE & REFIT REAR COMPARTMENT CARPET & FITTING.		150.00	80.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREA.		80.00	30.00
	TO RUST PROOF ON REPAIRED AREAS .		80.00	30.00
	TO SPRAY PAINT ON REPAIRED AREAS .		800.00	600.00
			2,140.00	1,550.00
	GRAND TOTAL		9,457.50	5,994.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CC4/FCI21012359/Ega3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 3433D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 3433D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 3433D

RE-INSPECTION

