

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012360/BPA3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070031935-01
Claimant Vehicle No :	SLU8888A	Insured Vehicle No :	SMS3993K
Date of Loss:	05/12/2021	Nature of Claim:	TP
		Claim No:	2419573050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU8888A		
Make & Model:	PORSCHE CAYENNE, 3.6 V6 E5 TIPTRONIC (A)	Engine No:	DCB023055
Reg. Date:	02/01/2019 (Man. Year: 2018)	Chassis No:	WP1ZZZ9YZKDA01505
Colour:	White	Odometer:	33146 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/40 R21	Rear Tyre Size:	315/35 R21
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	76,014.15	50,968.14	25,046.01	32.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	1,580.00	3,020.00	65.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	80,614.15	52,548.14	28,066.01	34.82
Approved Total (Overridden) (S\$)		42,000.00		
(S\$)	80,614.15	42,000.00	38,614.15	47.90
+ GST 7.00/7.00% (S\$)	5,642.99	2,940.00	2,702.99	47.90
Nett Amount (S\$)	86,257.14	44,940.00	41,317.14	47.90
+ Car Rental (10.0 x S\$160.00/day + 7.00% GST) (S\$)		1,712.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		46,779.45		
Global Sum Settlement (S\$)		46,770.00		

INSPECTION

Date of Assignment:	07/12/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	07/12/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	7.0 days	Singapore 575722

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET LOGO	Necessary	235.00 FL	*210.00 FL
2	2		*BONNET LOCK	Not Damaged	597.40 FL	*- FL
3	2		*BONNET LOCK UPPER LATCH	Not Damaged	524.00 FL	*- FL
4	1		*BONNET INNER RUBBER	Dislodged	380.00 FL	*73.50 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	384.00 FL	*268.20 FL
6	1		*FRONT BUMPER SIDE CARRIAGE RH	Broken	178.00 FL	*60.00 FL
7	1		*FRONT BUMPER SUPPORT TOP PANEL	Dented	468.50 FL	*230.00 FL
8	1		*FRONT BUMPER TOW COVER	Cut	102.00 FL	*95.00 FL
9	1		*FRONT BUMPER SIGNAL LAMP RH	Broken	833.80 FL	*349.00 FL
10	1		*FRONT BUMPER SIGNAL GARNISH	O/S Broken	1,017.20 FL	*508.60 FL
11	1		*FRONT BUMPER SIGNAL INNER BASE GARNISH	Broken	488.00 FL	*488.00 FL
12	2		*FRONT BUMPER LOWER SIDE GARNISH	Cut	229.20 FL	*60.00 FL
13	1		*FRONT BUMPER CENTRE GRILLE	Broken	1,854.00 FL	*304.60 FL
14	1		*FRONT BUMPER LOWER COVER	Not Damaged	579.40 FL	*- FL
15	1		*FRONT BUMPER INNER SPONGE	Broken	397.60 FL	*288.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	1,487.70 FL	*- FL
17	4		*FRONT BUMPER PARKING SENSOR	Scratched (2 PCS ONLY)	1,584.80 FL	*570.00 FL
18	1		*FRONT BUMPER LISENCE PLATE	Missing	122.30 FL	*80.00 FL
19	1		*FRONT AIR DUCT WITH CONTROL	Broken	1,921.00 FL	*550.00 FL
20	1		*FRONT AIR DUCT BOTTOM	Broken	843.50 FL	*136.00 FL
21	1		*FRONT AIR DUCT BOTTOM OUTER GARNISH	No such part	447.00 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Dented	2,447.90 FL	*1,660.40 FL
23	1		*FRONT SUPPORT TOP PANEL	Dented	1,292.60 FL	*570.00 FL
24	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	126.10 FL	*126.10 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH RUBBER	No such part	89.00 FL	*- FL
26	1		*FRONT ENGINE SIDE COVER	Not Damaged	187.00 FL	*- FL
27	1		*FRONT BRACE PANEL	Not Damaged	342.50 FL	*- FL
28	1		*AIR INTAKE DUCT	Not Damaged	176.00 FL	*- FL
29	2		*HEADLAMP	Broken	16,245.00 FL	*10,276.00 FL
30	1		*HEADLAMP BRACKET	O/S Broken	410.00 FL	*315.70 FL
31	1		*A/C CONDENSER	Not Damaged	2,864.40 FL	*- FL
32	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
33	1		*BONNET (TECHART) CARBON FIBRE	Broken	15,800.00 FS	*14,500.00 FS
34	1		*FRONT BUMPER (TECHART)	Broken	10,790.00 FS	*9,500.00 FS
35	1		*FRONT BUMPER LOWER (TECHART)	Broken	6,700.00 FS	*6,000.00 FS
36	1		*FRONT BUMPER DIFFUSER (TECHART)	Broken	3,880.00 FS	*3,500.00 FS
37	1		*FRONT BUMPER DIFFUSER CENTRE GARNISH	Broken	680.00 FS	*500.00 FS
38	1		*FRONT BUMPER DIFFUSER CENTRE BRACKET	Bent	500.00 FS	*450.00 FS
39	1		*FRONT BUMPER CLIPS	No such part	60.00 FS	*- FS
40	1		*FRONT BUMPER LOWER CLIPS	Necessary	60.00 FS	*- FS
41	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
42	4		*FRONT BUMPER PARKING SENSOR SEAL	Necessary (2 PCS ONLY)	192.00 FS	*70.00 FS
43	1		*A/C FLUID	Not Necessary	100.00 FS	*- FS
44	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
45	1		*FRONT NUMBER PLATE W/CASING	Missing	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	77,956.90	51,829.10
- List Item Discount on L Items 5.00/5.00% (\$)	1,942.75	860.96
Total Parts (\$)	76,014.15	50,968.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT BUMPER PARKING SENSOR	New	150.00	60.00
2	R&R A/C CONDENSER	New	150.00	0.00
3	R&R RADIATOR	New	150.00	0.00
4	CHECK WIRING	New	150.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	DIAGNOSTIC & RESET FAULT CODE	New	300.00	120.00
7	PANEL BEATING	New	1,600.00	800.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINTING	New	1,600.00	600.00
Gross Labour Cost (\$\$)			4,600.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >