

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III21012361/BQF3E2-1

**Date:** 06/07/2022

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SLZ4666Z **Insured Vehicle No :** SMR5917Z  
Date of Loss: 27/11/2021 Nature of Claim: TP Claim No: MFL2021D0005199

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ4666Z**  
Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR8374254  
Reg. Date: 04/05/2018 (Man. Year: 2018) Chassis No: ZVW506117985  
Colour: Silver Odometer: 111853 km  
Engine Capacity: 1797 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,367.29	2,748.35	9,618.94	77.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,680.00	1,960.00	53.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,007.29</b>	<b>4,428.35</b>	<b>11,578.94</b>	<b>72.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>16,007.29</b>	<b>3,550.00</b>	<b>12,457.29</b>	<b>77.82</b>

### INSPECTION

Date of Assignment: 07/12/2021  
Date Inspected: 13/12/2021 Inspected At: 160 Sin Ming Drive #05-17, Sin Ming Autocity  
Estimated Period of Repair: 5.0 days Repairer: Hiap Lek Automobile Trading

**Adjuster:** Lim Teow Guan

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2022)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ4666Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	1,350.90 F	*- FL
2	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	255.90 F	*- FL
3	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	390.65 F	*- FL
4	1		*FRONT DOOR LOCK RH	Not Necessary	650.80 F	*- FL
5	1		*CENTRE DOOR PILLAR RH	Repair	355.95 F	*- FL
6	1		*ROCKER PANEL GARNISH RH	Cut	598.90 F	*598.90 FL
7	1		*ROCKER PANEL RH	Repair	496.60 F	*- FL
8	1		*REAR DOOR RH	Dented / Bent	1,298.90 F	*1,182.00 FL
9	1		*REAR DOOR OUTER HANDLE RH	Repair	365.99 F	*- FL
10	1		*REAR DOOR INNER HANDLE ASSY RH	Serviceable	220.80 F	*- FL
11	1		*REAR DOOR LOCK RH	Bent	538.90 F	*475.00 FL
12	1		*REAR DOOR TOP HINGE RH	Serviceable	181.90 F	*- FL
13	1		*REAR DOOR BOTTOM HINGE RH	Serviceable	181.90 F	*- FL
14	1		*REAR DOOR CHECKER RH	Bent	189.90 F	*189.90 FL
15	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	755.60 F	*- FL
16	1		*REAR DOOR INNER TRIM BOARD SPEAKER RH	Not Necessary	320.00 F	*- FL
17	1		*REAR DOOR WINDOW GLASS REGULATOR GEAR	Bent	850.90 F	*229.00 FL
18	1		*REAR DOOR WEATHERSTRIP RH	Necessary	281.80 F	*175.00 FL
19	1		*REAR FENDER RH	Repair	899.60 F	*- FL
20	1		*REAR SHOCK ABSORBER RH	Not Necessary	155.90 F	*- FL
21	1		*REAR LOWER ARM RH	Not Necessary	265.50 F	*- FL
22	1		*REAR KNUCKLE ARM RH	Not Necessary	530.00 F	*- FL
23	1		*REAR KNUCKLE ARM BEARING RH	Bent	248.00 F	*248.00 FL
24	1		*REAR TORSION ARM RH	Not Necessary	325.00 F	*- FL
25	1		*REAR DRAG LINK RH	Not Necessary	175.00 F	*- FL
26	1		*SET REAR DOOR INNER TRIM BOARD CLIP RH	Necessary	32.00 FS	*25.00 FS
27	1		*REAR SPORT RIM RH	Cut	450.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,367.29	3,522.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	774.45
Total Parts (\$\$)	12,367.29	2,748.35

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE - REFIT, PANEL BEAT, STRAIGHTEN, RE-ALIGN AND REPAIR OF FRONT RH DOOR, FRONT RH DOOR CENTRE PILLAR, ROCKER PANEL, ROCK PANEL GARNISH, REAR DOOR RH, REAR RH FENDER AND OTHERS RELEVANT ACCIDENT DAMAGES	New	1,400.00	600.00
2	TO REMOVE - REFIT REAR RH UNDER CARRIAGE DAMAGE PARTS	New	300.00	80.00
3	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	60.00
4	TO CHECK WIRINGS AND LIGHTINGS	New	50.00	30.00
5	TO SUPPLIED AND APPLIED ANTI RUST TREATMENT TO AFFECTED PANELS	New	180.00	50.00
6	TOWING CHARGES	New	80.00	0.00
7	TO TRANSFER RH DOORS FITTINGS AND ATTACHMENTS	New	150.00	60.00
8	TO PUTTY AND SPRAY PAINTING CHARGES	New	1,400.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,640.00</b>	<b>1,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >