

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012365/AVY3N2**Date:** 25/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00152572100
Claimant Vehicle No :	SMJ6589Y	Insured Vehicle No :	SCV32G
Date of Loss:	04/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207081/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6589Y	Engine No:	LEB1442675
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP51335477
Reg. Date:	14/03/2019 (Man. Year: 2018)	Odometer:	32996 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,253.00	1,521.60	1,731.40	53.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,355.00	430.00	925.00	68.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,608.00	1,951.60	2,656.40	57.65
+ GST 7.00/7.00% (\$\$)	322.56	136.61	185.95	57.65
Nett Amount (\$\$)	4,930.56	2,088.21	2,842.35	57.65

INSPECTION

Date of Assignment:	10/12/2021	SK Automobile Pte Ltd (HQ)
Date Inspected:	07/12/2021 Inspected At:	23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
Estimated Period of Repair:	2.0 days	Singapore 415933

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2022)
Parts:	144	HONDA FIT 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ6589Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT HEADLAMP RH	Not Necessary	936.00 FL	*- FL
2	1	*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	42.90 FL	*- FL
3	1	*FRONT GRILLE	Cracked	321.80 FL	*321.80 FL
4	1	*FRONT GRILLE LOGO EMBLEM	Necessary	25.30 FL	*25.30 FL
5	1	*FRONT GRILLE CHROME GARNISH UPPER	Not Necessary	224.30 FL	*- FL
6	1	*FRONT GRILLE CHROME MOULDING LOWER	Cut	341.30 FL	*341.30 FL
7	1	*FRONT BUMPER	Deformed	872.20 FL	*725.00 FL
8	1	*FRONT BUMPER TOW HOOK COVER	Not Necessary	29.30 FL	*- FL
9	1	*FRONT BUMPER LOWER CENTER GRILLE	Cracked	243.80 FL	*243.80 FL
10	1	*FRONT BUMPER LOWER CENTER GRILLE SIDE GARNISH LH/RH	O/s Cracked	39.00 FL	*19.50 FL
11	1	*FRONT BUMPER FOG LAMP COVER RH	Cracked	68.30 FL	*68.30 FL
12	2	*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	39.00 FL	*- FL
13	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	321.80 FL	*- FL
14	1	*FRONT BUMPER LOWER UNDER COVER	Not Necessary	273.00 FL	*- FL
15	1	*AIRCON CONDENSER AIR GUIDE RH	Torn	19.50 FL	*19.50 FL
16	1	*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
17	1	*SET FRONT BUMPER NUMBER PLATE WITH CASING	Cracked	85.00 FS	*60.00 FS
18	1	*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,012.50	1,874.50
- List Item Discount on L Items 20.00/20.00% (\$)	759.50	352.90
Total Parts (\$)	3,253.00	1,521.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	600.00	200.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	600.00	200.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	75.00	0.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
Gross Labour Cost (S\$)			1,355.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >