

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012369/AQY3N2**Date:** 08/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00115122101

Claimant Vehicle No : SMZ9857U **Insured Vehicle No :** GBK6101X

Date of Loss: 06/12/2021 Nature of Claim: TP Claim No: SNM21D207063/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ9857U**

Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B5578933

Reg. Date: 28/05/2021 (Man. Year: 2020) Chassis No: RU11328893

Colour: White Odometer: 1517 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,608.96	6,140.96	13,468.00	68.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	1,560.00	2,780.00	64.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,948.96	7,700.96	16,248.00	67.84
Approved Total (Overridden) (\$\$)		6,100.00		
Nett Amount (\$\$)	23,948.96	6,100.00	17,848.96	74.53

INSPECTION

Date of Assignment: 10/12/2021

Date Inspected: 07/12/2021 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ9857U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (UPPER)	Deformed	927.50 FL	*765.00 FL
2	1	*FRONT BUMPER (LOWER)	Cut	651.10 FL	*351.00 FL
3	2	*FRONT BUMPER FOGLAMP	Not Necessary	1,090.00 FL	*- FL
4	2	*FRONT BUMPER FOGLAMP COVER	Not Necessary	98.00 FL	*- FL
5	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	294.00 FL	*- FL
6	1	*FRONT BUMPER SIDE RETAINER	N/s Damaged	46.00 FL	*23.00 FL
7	2	*FRONT BUMPER REINFORCEMENT TOP GARNISH	Not Necessary	390.00 FL	*- FL
8	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	596.00 FL	*- FL
9	1	*FRONT BUMPER TOWING COVER	Not Necessary	25.00 FL	*- FL
10	1	*FRONT FENDER LH	Distorted	748.80 FL	*630.00 FL
11	1	*FRONT FENDER INNER COWLING	Deformed	130.80 FL	*130.80 FL
12	2	*FRONT FENDER ARCD GARNISH	Cracked	306.00 FL	*175.00 FL
13	1	*FRONT RESONATOR BOX	Cracked	210.40 FL	*210.40 FL
14	1	*FRONT WHEEL HOUSE EXTENT PANEL LH	Dented	210.40 FL	*210.40 FL
15	1	*FRONT WHEEL HOUSE SUPPORT PANEL LH	Repair	210.40 FL	*- FL
16	1	*GRILLE LOGO	Not Necessary	28.00 FL	*- FL
17	1	*GRILLE LOGO GARNISH (CHROME)	Not Necessary	845.00 FL	*- FL
18	1	*CENTRE GRILLE	Not Necessary	1,495.00 FL	*- FL
19	1	*CENTRE GRILLE SUPPORT BRACKET	Not Necessary	142.00 FL	*- FL
20	1	*HEADLAMP (LED)	N/s Cracked	7,968.00 FL	*3,318.00 FL
21	2	*HEADLAMP TOP CHROME	Not Necessary	796.00 FL	*- FL
22	2	*HEADLAMP SIDE BRACKET	Not Necessary	150.00 FL	*- FL
23	1	*HEADLAMP LOWER BRACKET (2 Pcs)	Cracked	168.00 FL	*84.00 FL
24	1	*BONNET	Not Necessary	1,468.00 FL	*- FL
25	1	*FRONT ABS SENSOR RH	Not Necessary	180.00 FL	*- FL
26	1	*FRONT SHOCK ABSORBER RH	Not Necessary	586.50 FL	*- FL
27	1	*FRONT LOWER ARM RH	Bent	474.70 FL	*474.70 FL
28	1	*FRONT KNUCKLE ARM RH	Not Necessary	461.70 FL	*- FL
29	1	*FRONT KNUCKLE ARM INNER BEARING RH	Damaged	262.00 FL	*262.00 FL
30	1	*FRONT WHEEL HUP RH	Damaged	379.40 FL	*379.40 FL
31	1	*FRONT LINKAGE RH	Not Necessary	65.00 FL	*- FL
32	1	*FRONT WHEEL RIM RH	Cut	896.00 FS	*450.00 FS
33	1	*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
34	1	*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
35	1	*SET FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
36	1	*SET FRONT FENDER ARCD GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
37	1	*SET FRONT FENDER INNER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
38	1	*SET CENTRE GRILLE CLIP	Not Necessary	30.00 FS	*- FS
39	1	*SET ENGINE UNDER CENTER COVER CLIP	Not Necessary	30.00 FS	*- FS
40	1	*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
41	1	*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
42	1	*SET RADIATOR SIDE GARNISH LH	Not Necessary	30.00 FS	*- FS
43	1	*SET FRONT FENDER COWLING CLIP	Repeated	50.00 FS	*- FS
44	1	*SET FRONT FENDER ARCD GARNISH CLIP	Repeated	50.00 FS	*- FS
45	1	*FRONT WHEEL RIM RH	Repeated	550.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*FRONT WHEEL TYRE RH	Not Necessary	450.00 FS	*- FS
47	1		*COOLANT	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	23,889.70	7,543.70
				- List Item Discount on L Items 20.00/20.00% (S\$)	4,280.74	1,402.74
				Total Parts (S\$)	19,608.96	6,140.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	1,400.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	700.00
3	REMOVE AND REFIX WIREHARNESS AND WIRING CHECKING	New	180.00	30.00
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	150.00
5	FOUR WHEEL ALIGNMENT	New	120.00	80.00
6	RESET ABS LIGHT	New	350.00	0.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,340.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >