

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21012372/KVF3E2

Date: 04/01/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100411644
Claimant Vehicle No : SME4701D Insured Vehicle No : SKR7510Z
Date of Loss: 03/12/2021 Nature of Claim: TP Claim No: 9197996891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME4701D**
Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU273503
Reg. Date: 29/09/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU762428
Colour: Metallic Grey Odometer: 41194 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Nexen 8 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 8 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,945.76	3,137.20	2,808.56	47.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,210.00	1,870.00	2,340.00	55.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,155.76	5,007.20	5,148.56	50.70
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,155.76	4,000.00	6,155.76	60.61

INSPECTION

Date of Assignment: 07/12/2021
Date Inspected: 08/12/2021 Inspected At: 160 Sin Ming Drive #08-03
Estimated Period of Repair: 5.0 days Repairer: T & B Motor Repairs Services Pte Ltd

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Bent	298.20 FL	*298.20 FL
2	1		*REAR BOOT COVER HINGE R/H	Distorted	115.00 FL	*115.00 FL
3	1		*REAR BOOT COVER HINGE L/H	Distorted	115.00 FL	*115.00 FL
4	1		*REAR BOOT COVER REFLECTOR RH	Split	284.00 FL	*284.00 FL
5	1		*REAR BOOT COVER REFLECTOR LH	Serviceable	284.00 FL	*- FL
6	1		*REAR BOOT INNER LOCK	Dented	146.00 FL	*146.00 FL
7	1		*REAR BOOT WEATHERSTRIP	Distorted / Dented	164.00 FL	*164.00 FL
8	1		*REAR BOOT LAMP RH	Serviceable	488.00 FL	*- FL
9	1		*REAR BOOT LAMP LH	Serviceable	488.00 FL	*- FL
10	1		*REAR BOOT END PANEL	Bent	654.00 FL	*455.00 FL
11	1		*REAR BOOT END PANEL TOP GARNISH	Serviceable	64.00 FL	*- FL
12	1		*REAR BOOT FLOOR BOARD COVER	Serviceable	249.00 FL	*- FL
13	1		*REAR BOOT WHEEL HOUSE GARNISH R/H	Serviceable	56.00 FL	*- FL
14	1		*REAR BUMPER	Cracked	795.00 FL	*498.00 FL
15	1		*REAR BUMPER SIDE RETAINER RH	Distorted	44.00 FL	*44.00 FL
16	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	44.00 FL	*- FL
17	1		*REAR BUMPER SIDE REFLECTOR R/H	Serviceable	40.00 FL	*- FL
18	1		*REAR BUMPER SIDE REFLECTOR L/H	Serviceable	40.00 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	494.00 FL	*294.80 FL
20	1		*REAR BUMPER LOWER CENTER BRACKET	Serviceable	28.00 FL	*- FL
21	1		*REAR BUMPER LOWER SIDE BRACKET L/H	Cracked	28.00 FL	*28.00 FL
22	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Repair	28.00 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Repair	48.00 FL	*- FL
24	10		*REAR BOOT COVER TRIM BOARD CLIPS	Not Necessary	65.00 FL	*- FL
25	10		*REAR BOOT WHEEL HOUSE GARNISH CLIP	Not Necessary	68.00 FL	*- FL
26	8		*REAR BUMPER CLIP	Necessary	44.00 FL	*44.00 FL
27	1		*REAR BOOT COVER LOGO	Necessary	68.00 FL	*68.00 FL
28	1		*REAR BOOT COVER (S) EMBLEM	Necessary	42.00 FL	*42.00 FL
29	1		*REAR BOOT COVER ELANTRA EMBLEM	Necessary	75.50 FL	*75.50 FL
30	1		*REAR BOOT NUMBER PLATE (EMBOSSSED)	Serviceable	80.00 FL	*- FL
31	1		*REAR BOOT INNER LOCK LOWER CATCH	Repair	58.00 FL	*- FL
32	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
33	1		*SET LOWER BODY KIT	Buckled	1,200.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,044.70	3,671.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,098.94	534.30
Total Parts (S\$)	5,945.76	3,137.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE BOOT LID INNER GARNISH	New	180.00	60.00
2	REMOVE REAR BOOT SPOILER AND SEALANT	New	250.00	100.00
3	REMOVE BOOT LID REVERSE CAMERA	New	220.00	50.00
4	CHECK AND REPAIR WIRING	New	80.00	20.00
5	SPRAY PAINT ANTI-RUST COATING	New	180.00	60.00
6	SPRAY PAINT ON END PANEL, FLOOR BOARD SPOILER, BODY KIT, BUMPER & REAR BOOT LID	New	1,500.00	880.00
7	PULL AND STRAIGHTEN FLOOR BOARD, REAR END PANEL, KNOCKING AND REPAIRS	New	1,800.00	700.00
			Gross Labour Cost (\$)	4,210.00
				1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >