

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21012373/AVF3Q2**Date:** 21/03/2022**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	MPC21P00110100
Claimant Vehicle No :	SMS8390S	Insured Vehicle No :	SGH7239H
Date of Loss:	19/11/2021	Nature of Claim:	TP
		Claim No:	DMPC2100408H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8390S	Engine No:	L15B6021119
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK82100947
Reg. Date:	17/03/2020 (Man. Year: 2019)	Odometer:	16916 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,801.36	4,751.76	2,049.60	30.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,070.00	1,680.00	44.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,551.36	6,821.76	3,729.60	35.35
Approved Total (Overridden) (S\$)		5,450.00		
Nett Amount (S\$)	10,551.36	5,450.00	5,101.36	48.35

INSPECTION

Date of Assignment:	07/12/2021	Sam Yick Lian (kaki bukit)
Date Inspected:	07/12/2021 Inspected At:	1 Kaki Bukit Ave 6, #01-70 Autobay @ KakiBukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Mar 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS8390S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,276.50 FL	*1,193.00 FL
2	1		*REAR BOOTLID UPPER LOCK	Damaged	168.20 FL	*168.20 FL
3	1		*REAR BOOTLID INNER BOARD	Cracked	439.30 FL	*295.00 FL
4	1		*REAR BOOTLID INNER WEATHERSTRIP	Cut	180.20 FL	*180.20 FL
5	1		*REAR BOOTLID CENTRE HANDLE	Not Necessary	185.00 FL	*- FL
6	1		*REAR BOOTLID H EMBLEM	Not Necessary	100.00 FL	*- FL
7	1		*REAR BOOTLID SHUTTLE EMBLEM	Necessary	80.00 FL	*80.00 FL
8	1		*REAR BUMPER	Deformed	1,230.00 FL	*1,050.00 FL
9	1		*REAR BUMPER CHROME MOULDING	Necessary	161.80 FL	*161.80 FL
10	1		*REAR BUMPER TOWING HOOK COVER	Deformed	18.10 FL	*18.10 FL
11	2		*REAR BUMPER REFLECTOR	Not Necessary	96.20 FL	*- FL
12	2		*REAR BUMPER BRACKET	Not Necessary	53.40 FL	*- FL
13	2		*REAR BUMPER SIDE BRACKET	Necessary	78.00 FL	*78.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Not Necessary	450.00 FL	*- FL
15	1		*REAR END PANEL	Dented	643.60 FL	*643.60 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	166.30 FL	*166.30 FL
17	2		*REAR LAMP	Cut	1,178.00 FL	*1,178.00 FL
18	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	380.00 FL	*- FL
19	1		*REAR SPARE TYRE TOOL BOX	Cracked	604.60 FL	*415.00 FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
21	1		*REAR TAILGATE LOCK SENSOR	Not Necessary	380.00 FS	*- FS
22	1		*SET REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,299.20	5,877.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,497.84	1,125.44
Total Parts (\$\$)	6,801.36	4,751.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE PANEL KNOCKING ON ACC PARTS	New	1,500.00	800.00
2	TO PROVIDE SPRAY PAINTING	New	1,300.00	800.00
3	REMOVE & REFIX REAR WINDSCREEN	New	200.00	120.00
4	REMOVE & REPLACE REVERSE SENSOR	New	100.00	50.00
5	REMOVE & REFIX CAMERA	New	100.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR	New	100.00	50.00
7	REMOVE AND REFIX UPHOLSTERY	New	150.00	60.00
8	TO TUFF COAT AFFECTED PANELS	New	150.00	60.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
Gross Labour Cost (S\$)			3,750.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >