

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21012374/AGA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJJ5132Z	Insured Vehicle No :	SMQ405Y
Date of Loss:	03/12/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0005278

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ5132Z	Engine No:	1NZD107383
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	NCP815064709
Reg. Date:	16/09/2008 (Man. Year: 2008)	Odometer:	299999 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,480.47	6,766.72	6,713.75	49.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,780.00	3,110.00	3,670.00	54.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,260.47	9,876.72	10,383.75	51.25
Approved Total (Overridden) (S\$)		7,900.00		
Nett Amount (S\$)	20,260.47	7,900.00	12,360.47	61.01
+ Loss of Use (11.0 x S\$50.00/day) (S\$)		550.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,486.45		
Global Sum Settlement (S\$)		8,450.00		

INSPECTION

Date of Assignment:	07/12/2021	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	07/12/2021 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	10.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2022)
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJJ5132Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	899.10 FL	*899.10 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	136.20 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	100.00 FL	*100.00 FL
4	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.10 FL	*- FL
5	1		*TAILLAMP	N/S Cut	1,170.00 FL	*585.00 FL
6	1		*TAILLAMP LOWER PANEL LH	Repair	1,170.00 FL	*- FL
7	1		*TAIL GATE	Distorted	921.10 FL	*921.10 FL
8	1		*TAIL GATE LOCK	Damaged	238.10 FL	*238.10 FL
9	1		*TAIL GATE CATCH	Not Necessary	25.00 FL	*- FL
10	1		*TAIL GATE INNER TRIM	Cracked	711.10 FL	*481.00 FL
11	1		*TAIL GATE LOGO	Necessary	115.10 FL	*115.10 FL
12	2		*TAIL GATE STOPPER	Not Necessary	30.20 FL	*- FL
13	1		*TAIL GATE EMBLEM SIENTA	Necessary	65.10 FL	*65.10 FL
14	1		*TAIL GATE INNER HOLDER GARNISH	Not Necessary	59.10 FL	*- FL
15	1		*TAIL GATE WEATHERSTRIP	Cut	265.10 FL	*265.10 FL
16	1		*SET TAIL GATE WINDSCREEN MOULDING	Necessary	128.10 FL	*128.10 FL
17	1		*TAIL GATE OUTER HANDLE GARNISH	Not Necessary	196.10 FL	*- FL
18	1		*REAR FENDER LH	Repair	984.60 FL	*- FL
19	1		*REAR FENDER QUARTER GLASS WITH MOULDING	Not Necessary	456.10 FL	*- FL
20	1		*REAR FENDER UPPER TRIM LH	Not Necessary	502.80 FL	*- FL
21	1		*REAR FENDER INNER PANEL LH	Repair	397.80 FL	*- FL
22	1		*REAR FENDER AIR VENT LH	Cracked	128.60 FL	*56.00 FL
23	1		*REAR WHEEL HOUSE PANEL LH	Repair	763.90 FL	*- FL
24	1		*REAR FENDER ARCH SEAL LH	Not Necessary	97.20 FL	*- FL
25	2		*REAR FENDER INNER TRIM BOARD	Cracked	1,400.20 FL	*1,122.00 FL
26	2		*REAR FENDER INNER COWLING	Not Necessary	170.20 FL	*- FL
27	1		*REAR END PANEL(OUTER)	Distorted	398.10 FL	*398.10 FL
28	1		*REAR END PANEL(INNER)	Distorted	591.10 FL	*591.10 FL
29	1		*REAR END PANEL TOP GARNISH	Cracked	198.40 FL	*198.40 FL
30	1		*REAR FLOOR PANEL	Distorted	921.50 FL	*921.50 FL
31	1		*FLOOR SIDE PANEL LH	Buckled	215.40 FL	*215.40 FL
32	1		*REAR INNER COVER BOARD	Deformed	515.60 FL	*305.00 FL
33	1		*REAR SPARE TYRE BOLT	Not Necessary	38.10 FL	*- FL
34	1		*REAR TOOL HOLDER GARNISH	Deformed	385.10 FL	*385.10 FL
35	1		*REAR TOOL COVER BOARD	Deformed	685.10 FL	*312.00 FL
36	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
37	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
38	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
39	1		*SET TAIL GATE OUTER HANDLE GARNISH CLIP	Not Necessary	30.00 FS	*- FS
40	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
41	1		*TAIL GATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*40.00 FS
42	1		*REAR FENDER LH SEALANT	Not Necessary	150.00 FS	*- FS
43	1		*REAR FENDER INNER PANEL SEALANT LH	Not Necessary	120.00 FS	*- FS
44	1		*REAR WHEEL HOUSE PANEL SEALANT LH	Not Necessary	150.00 FS	*- FS
45	1		*REAR FENDER GLASS SEALANT LH	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER GLASS INNER SEAL LH	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR FENDER INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
48	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
49	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
50	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
51	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
52	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	250.00 FS	*60.00 FS
53	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
54	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
55	1		*PRIVATE HIRE DECAL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,257.30	8,842.30
- List Item Discount on L Items 25.00/25.00% (\$)	3,776.83	2,075.58
Total Parts (\$)	13,480.47	6,766.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	2,200.00	1,400.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,200.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	150.00	80.00
6	REMOVE & REINSTALL REAR SAFETY BELT	New	250.00	0.00
7	REMOVE AND REFIX REAR FENDER GLASS	New	100.00	0.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
10	REAR CHASSIS ALIGNMENT	New	250.00	0.00
11	TRANFER TAILGATE MECHANISM	New	80.00	80.00
12	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
13	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
14	REMOVE AND REFIX REAR UNDERCARRIAGE	New	600.00	0.00
15	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER LH REPLACEMENT	New	120.00	0.00
16	REMOVE AND REFIX REAR EXHAUST PIPE TO FACILITATE FLOOR PANEL REPLACEMENT	New	120.00	0.00
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			6,780.00	3,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >