

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012376/GGA3Q2**Date:** 08/08/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100495762
<b>Claimant Vehicle No :</b>	SLN6623Y	<b>Insured Vehicle No :</b>	SLJ8269U
Date of Loss:	02/12/2021	Nature of Claim:	TP
		Claim No:	4237057872SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLN6623Y</b>	Engine No:	2NR8664365
Make & Model:	TOYOTA COROLLA AXIO, 1.5 G (A)	Chassis No:	NRE1610020955
Reg. Date:	12/05/2017 (Man. Year: 2016)	Odometer:	332425 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	INTERTRAC 6 mm	Rear Left Side:	INTERTRAC 6 mm
Front Right Side:	INTERTRAC 6 mm	Rear Right Side:	INTERTRAC 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,910.92	4,905.52	8,005.40	62.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	2,030.00	3,970.00	66.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,910.92</b>	<b>6,935.52</b>	<b>11,975.40</b>	<b>63.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>18,910.92</b>	<b>5,500.00</b>	<b>13,410.92</b>	<b>70.92</b>
<b>+ Loss of Use (7.0 x S\$50.00/day) (S\$)</b>		350.00		
<b>+ Doc/Search Fee (S\$)</b>		31.00		
<b>+ Other Costs (S\$)</b>		60.00		
<b>Nett Liability (S\$)</b>		<b>5,941.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,900.00</b>		

**INSPECTION**

Date of Assignment:	07/12/2021	PROVI AUTOWORKS PTE LTD (HQ)
Date Inspected:	07/12/2021 Inspected At:	8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki Bukit
Estimated Period of Repair:	7.0 days	Singapore 415875

**Adjuster:** XING GUO QIANG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	954.00 FL	*895.00 FL
2	1		*BOOTLID LOGO	Necessary	85.00 FL	*85.00 FL
3	1		*BOOTLID EMBLEM (COROLLA)	Necessary	87.60 FL	*45.00 FL
4	1		*BOOTLID EMBLEM (AXIO)	Necessary	126.00 FL	*60.00 FL
5	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	452.00 FL	*- FL
6	2		*BOOTLID CAR PLATE LAMP	Not Necessary	116.00 FL	*- FL
7	1		*BOOTLID OPENER SWICTH	Not Necessary	211.70 FL	*- FL
8	1		*BOOTLID INNER LOCK	Bent	317.50 FL	*317.50 FL
9	1		*BOOTLID LOCK CATCH	Not Necessary	35.00 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	215.00 FL	*175.00 FL
11	1		*BOOTLID INNER TRIM	Not Necessary	395.00 FL	*- FL
12	2		*BOOTLID HINGE	Not Necessary	424.00 FL	*- FL
13	2		*TAILLAMP	Cracked	1,396.00 FL	*1,170.00 FL
14	2		*TAILLAMP INNER GASKET	Not Necessary	152.60 FL	*- FL
15	2		*TAILLAMP PANEL	Buckled (1 PCS ONLY)	504.00 FL	*150.00 FL
16	2		*TAILLAMP LOWER BRACKET	Broken	152.00 FL	*152.00 FL
17	1		*REAR BUMPER	Deformed	665.00 FL	*596.20 FL
18	2		*REAR BUMPER SIDE RETAINER	Broken (1 PCS ONLY)	370.00 FL	*96.00 FL
19	2		*REAR BUMPER REFLECTOR	Broken (1 PCS ONLY)	250.00 FL	*48.20 FL
20	2		*REAR BUMPER DAMPER	Bent (1 PCS ONLY)	332.80 FL	*65.00 FL
21	1		*REAR FENDER LH	Repair	1,036.40 FL	*- FL
22	2		*REAR FENDER INNER TRIM	Torn (1 PCS ONLY)	716.00 FL	*263.10 FL
23	2		*REAR FENDER INNER SHIELD	Torn (1 PCS ONLY)	192.00 FL	*96.00 FL
24	1		*REAR FENDER AIR VENT	Not Necessary	55.00 FL	*- FL
25	1		*REAR WINDSCREEN MOULDING	Not Necessary	154.00 FL	*- FL
26	1		*REAR END PANEL	Buckled	696.30 FL	*608.00 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	280.00 FL	*227.00 FL
28	1		*REAR FLOOR PANEL	Repair	785.00 FL	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Bent	542.00 FL	*542.00 FL
30	1		*REAR FLOOR TOOL SPONGE	Cracked	325.00 FL	*325.00 FL
31	1		*REAR DOOR INNER LOCK LH	Not Necessary	452.00 FL	*- FL
32	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	215.00 FL	*- FL
33	1		*DRIVER SEAT BELT	Not Necessary	954.00 FL	*- FL
34	1		*SRS AIRBAG CONTOR UNIT	Not Necessary	1,245.00 FL	*- FL
35	1		*ANTENNA SENSOR	Damaged	379.00 FL	*144.70 FL
36	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
37	1		*BOOT LID INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
38	1		*BOOT LID OUTER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
39	1		*TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS
40	1		*TAIL LAMP PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
41	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
42	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
43	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
45	1		*REAR FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*20.00 FS
46	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
47	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
48	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
50	1		*REVERSE SENSOR	Damaged	450.00 FS	*200.00 FS
51	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
52	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 16,727.90 6,420.70**  
**- List Item Discount on L Items 25.00/25.00% (\$\$) 3,816.98 1,515.18**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (S\$)</b>	<b>12,910.92</b>	<b>4,905.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	200.00	60.00
4	WIRING CHECK	New	50.00	30.00
5	REMOVE AND REFIX CUSHION SEAT AND INTERIOR TO FACILITATE REPAIR	New	450.00	60.00
6	REMOVE AND REFIX REAR WINDSCREEN	New	200.00	0.00
7	REMOVE AND INSTALL REAR EXHAUST	New	350.00	0.00
8	TRANFER BOOTLID MECHANISM	New	150.00	40.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	40.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	RESET SRS AIRBAG SYSTEM	New	550.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,000.00</b>	<b>2,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >