

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

FRE-REFAIR INSPECTION REFORT						
	MS FIRST CAPITA	L INSURANCE LTD	Re	ef:	CS3/FCI21012377/Uvf3e2	
	36 ROBINSON RO SINGAPORE 0688	AD #16-01 CITY HOUSE 77	Da	ate:	17/12/2021	
			Co	ode:	FCI2	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBF 5729T	Veh. Inspected		GBL 2360K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D21003381MFCV	Excess (\$)		0.00	
	Assign From	JOANNE TAN JO ANN	Assign Date		07/12/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE (A)	c.c		2754	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	GDH2012018510	Colour		SILVER	
	Odometer	320 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/80 R15	DUNLOP		7 mm	
	L/H Front Tyre	195/80 R15	DUNLOP		7 mm	
	R/H Rear Tyre	195/80 R15	DUNLOP		7 mm	
	L/H Rear Tyre	195/80 R15	DUNLOP		7 mm	
4. Description of Damages						
	THE VEHICLE SUS	EHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	03/12/2021	Inspect Date / Tim	ne	07/12/2021 (03:30 PM)	
	Survey held at SPEEDWERKZ PTE LTD					
	13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807					
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$80,000.00					

Report Ref No. CS3/FCI21012377/Uvf3e2

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE