

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21012378/GVF3E2

Date: 12/01/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993629
Claimant Vehicle No : FBN6801T **Insured Vehicle No :** SMS5719Z
Date of Loss: 24/11/2021 Nature of Claim: TP Claim No: 6071878564SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN6801T**
Make & Model: YAMAHA AEROX 155A, 155cc Engine No: G3J1E0256919
Reg. Date: 20/11/2018 (Man. Year: 2018) Chassis No: MH3SG4610JJ152907
Colour: Yellow Odometer: 33180 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 140/70-14
Front Left Side: IRC 5 mm Rear Left Side: IRC 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/12/2021
Date Inspected: 08/12/2021 Inspected At: Equator Brotherhood (HQ)
25 kaki bukit rd 4 #03-79 synergy @ kb
Singapore 417800
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$10,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK ASSY	Repair	0.00 F	*- F
3	1		*FRONT HEADLAMP FAIRING RH	Cut	0.00 F	*- F
4	1		*FRONT WING MIRROR RH	Missing	0.00 F	*- F
5	1		*HANDLE BAR	Bent	0.00 F	*- F
6	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
7	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
8	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
9	1		*FRONT TOP FAIRING INNER GARNISH	Distorted	0.00 F	*- F
10	1		*RH STEP BOARD GARNISH	Cut	0.00 F	*- F
11	1		*RH STEP BOARD	Cut	0.00 F	*- F
12	1		*RH STEP BOARD PLATE	Cut	0.00 F	*- F
13	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
14	1		*EXHAUST MUFFLER ASSY	Cut	0.00 F	*- F
15	1		*EMBLEM	Cut	0.00 F	*- F
16	1		*STICKER	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >