



















Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 01 Sep 2021 / 21:11:00)

Vehicle Insurance Details

Vehicle No.:

SGK4226Z

Make Description/Model:

TOYOTA / WISH 1.8 A

Insurance Company Name:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Business Transaction Reference No.:

20210902112241551308

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Save as PDF

OK →

Print

Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 01 Sep 2021 / 21:11:00)

Vehicle Insurance Details

Vehicle No.:

SLL3255G

Make Description/Model:

MAZDA / MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Insurance Company Name:

MSIG INSURANCE (SINGAPORE) PTE LTD

Insurance Company Name:

INDIA INT'L INS PTE LTD

Business Transaction Reference No.:

20210902112358917773

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Disclaimer message:

Your search is displaying 2 records as there is an overlap in the period covered by the insurance policies. You may wish to contact the insurance companies for more information.

Save as PDF

OK →

Print



Thank you

Constance Margreat Paglar has successfully logged out.

Your last login date and time was 02 Sep 2021, 11:22:03.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No. 	Asset Type 	Asset ID 	Asset Owner ID 	Transaction Type 	Transaction 
1	Vehicle	SLL3255G	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
2	Vehicle	SGK4226Z	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Date of Request: 16/09/2021

Your Ref No: CP/8423/21/PD (ACS)- WL (sf)

Dear Sir/Madam,

Date of Accident: 01/09/2021 00:00 (SGT)

Vehicle No: SKC 1297H

Place of Accident: Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SGK 4226Z	Singapore	(29.00)	1	(27.10)
GST Amount				(1.90)
Total Amount Due (GST Inclusive)				(29.00)

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Date of Request: 16/09/2021

Your Ref No: CP/8423/21/PD (ACS)- WL (sf)

Dear Sir/Madam,

Date of Accident: 01/09/2021 00:00 (SGT)

Vehicle No: SKC 1297H

Place of Accident: CTE, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLL 3255G	CTE, Singapore	(29.00)	1	(27.10)
GST Amount				(1.90)
Total Amount Due (GST Inclusive)				(29.00)

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

Alpha Car Services Pte Ltd

Blk C, Kaki Bukit Ave 6, #01-59 Kaki Bukit Autobay Singapore 417883

Tel: 6509 8258

Email: alphacarservices@hotmail.com

(GST REG No: 201717633Z) (ROC No: 201717633Z)

PROFORMA TAX INVOICE

BILL TO : MR. LOH KOK MUN
NRIC/UEN : S7837395D
C/O ADDRESS : BLK C KAKI BUKIT AVE 6
#01-59 KAKI BUKIT AUTOBAY
SINGAPORE 417883.
VEHICLE REG.No : SKC 1297H
MAKE & MODEL : HONDA CRV
CHASSIS No : JHLRE28308C201324

REF NO : 2109-0539
DATE : 27TH OCTOBER 2021
CLAIM REF : CPC[CHINA]PD
DOA : 01/09/021

Description	Amount
- To dismantle / renew the accident damaged portion.	\$ 7,250.00
- To panel beat, reshape, straighten, orientate and align repair / replacement parts.	
- To supply spray paint material and necessary items to respray affected area / panel.	

Singapore Dollars : Seven Thousand Seven Hundred And Fifty Seven And Cents Fifty Only

TOTAL	\$ 7,250.00
GST 7.00 %	\$ 507.50
AMOUNT DUE	<u>\$ 7,757.50</u>

KINDLY INDICATE YOUR REF NUMBER

Payment options

- 1) Cheque : Please issue cheque for exact amount made payable to "Alpha Car Services Pte Ltd "
- 2) Interbank transfer : Payment by Telegraphic Transfer should be made payable to: United Overseas Bank
SGD Account No : 378-305-347-9 Bank Code : 7375 SWIFT Code : UOVBSGSGXXX
- 3) PAYNOW UEN : 201717633Z



Authorised Signature

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singapore 415874
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

INVOICE

To : Loh Kok Mun
c/o : Alpha Car Services Pte Ltd
1 Kaki Bukit Ave 6 Blk C
#01-59 Autobay@Kakit Bukit
Singapore 417883

Date : 08 Oct 2021

Invoice No. : P 8093964

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	SGD 638.00
Photographs 43 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Total	SGD 638.00
Singapore dollar : SIX HUNDRED THIRTY EIGHT ONLY.	
Registration no. : SKC1297H	
Make/Model : Honda CRV 2.0L AT	
Our reference : UAM21.09.03-AK-STP-ACS-SKC1297H	
All payments made payee to:- " UNITED APPRAISAL & MANAGEMENT PTE LTD "	



for UNITED APPRAISAL & MANAGEMENT PTE LTD

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singapore 415874
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

Our ref. : UAM21.09.03-AK-STP-ACS-SKC1297H

Date : 08 Oct 2021

Loh Kok Mun

WITHOUT PREJUDICE

Dear Sir,

Re : Third Party Claim For Vehicle Registration No. SKC1297H

We refer to your instruction to appraise the above-mentioned vehicle on 06 September 2021

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Alpha Car Services Pte Ltd for SGD 12,612.14 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 9,063.15. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 7,250.00 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 7 (Seven) days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 10 Kaki Bukit Ave 4 #06-75 Premier @ Kaki Bukit Singapore 415874
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Loh Kok Mun

Our ref. : UAM21.09.03-AK-STP-ACS-SKC1297H

Date : 08 Oct 2021

REFERENCE

Assign by	: Loh Kok Mun	Insured	: To be advice
Assign on	: 06 Sep 2021	Policy no.	: To be advice
Inspection on	: 06 Sep 2021	Claim no.	: To be advice
Accident on	: 01 Sep 2021	Sum insured	: To be advice
Workshop name	: Alpha Car Services Pte Ltd	Excess	: Not applicable
Inspection at	: 1 Kaki Bukit Ave 6 Blk C #01-59 Autobay@Kakit Bukit Singapore 417883	3rd party Veh.	: To be advice
		3rd party ins.	: To be advice

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SKC1297H	Odometer	: 254783 km
Make / Model	: Honda CRV 2.0L AT	Chassis no.	: JHLRE28308C201324
Regn. date	: 29 Apr 2008	Engine no.	: R20A12701243
Body colour	: Silver	Engine cap.	: 1997 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE

	Make	Size	Tread depth	Type of road wheel
Front N/S	: Bridgestone	225/60R16	70%	Alloy
Front O/S	: Bridgestone	225/60R16	70%	Alloy
Rear N/S	: Bridgestone	225/60R16	70%	Alloy
Rear O/S	: Bridgestone	225/60R16	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

On the rear from the direction rear to front.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the tailgate, rear bumper, rear side bumpre, rear end panel, spare tyre panel and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 07 Sept 2021 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Alpha Car Services Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 7,250.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 7 (Seven) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SKC1297H

Our reference : UAM21.09.03-AK-STP-ACS-SKC1297H

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LIST ITEMS</u>					
1	1	Tailgate	Dented	1231.00	1231.00
2	1	Tailgate emblem " CRV "	Necessary	43.60	43.60
3	1	Tailgate logo	Necessary	79.80	79.80
4	1	Tailgate lower outer garnish	Damaged	474.80	474.80
5	1	Tailgate outer handle	Not Necessary	172.10	0.00
6	1	Tailgate inner lock	Distorted	293.80	293.80
7	1	Tailgate weatherstrip	Necessary	154.20	154.20
8	1	Tailgate trimboard	Re-Used	462.00	0.00
9	1	Tailgate windscreen moulding	Necessary	126.00	126.00
10	1	Rear bumper	Deformed	786.00	786.00
11	2	Rear bumper retainer @ SGD 119.70	Distorted	239.40	239.40
12	2	Rear bumper side @ SGD 376.60	O/S Deformed	753.20	376.60
13	1	Rear bumper defuser	Damaged	672.14	672.14
14	2	Rear bumper reflector @ SGD 94.00	O/S Cracked	184.00	94.00
15	1	Rear end panel	Buckled	617.00	617.00
16	1	Rear end panel top garnish	Deformed	98.20	98.20
17	1	Spare tyre panel	Buckled	1204.90	1204.90
				7592.14	6491.44
				Less 0% / 20%	0.00
					1298.29
				7592.14	5193.15
<u>SPECIAL NETT ITEMS</u>					
1	1	Sundries	Necessary	50.00	30.00
2	1set	Tailgate outer garnish clips	Necessary	40.00	40.00
3	1set	Tailgate trimboard clips	Necessary	45.00	45.00
4	1	Tailgate windscreen primer and cleaner	Necessary	100.00	80.00
5	1	Tailgate windscreen inner seal	Necessary	60.00	40.00
6	1	Tailgate windscreen sealant	Necessary	80.00	60.00
7	1set	Rear bumper clips	Necessary	80.00	80.00
8	2set	Rear bumper side clips @ SGD 35.00	Necessary	70.00	70.00
9	1set	Rear bumper defuser clips	Necessary	30.00	30.00
10	1	Rear end panel sealant	Necessary	100.00	80.00
11	1set	Rear end panel top garnish clips	Necessary	25.00	25.00
12	1	Spare tyre panel sealant	Necessary	100.00	80.00
13	1	Reverse sensor with module	Shorted	300.00	280.00
				1080.00	940.00
TOTAL				8672.14	6133.15

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SKC1297H

Our reference : UAM21.09.03-AK-STP-ACS-SKC1297H

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	SGD 350.00/day	1800.00	1400.00
2		To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	60.00
3		To remove and refit rear windscreen to facilitate the repair.		180.00	150.00
4		To remove and refit tailgate component to replace tailgate, check and re-adjust the close gap and alignment and water seepage.		100.00	80.00
5		To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test on the distance and functions.		80.00	60.00
6		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00
7		Supply spray paint material and necessary items to respray tailgate, rear bumper sides, rear end panel, spare tyre panel and other affected area / panel.	SGD 250.00/pnl	1500.00	1000.00
TOTAL				3940.00	2930.00
Total Parts and Labour Cost of Repair				12612.14	9063.15
Less (Lumpsum repair adjustment)					1813.15
Adjustment Parts and Labour Cost of Repair					7250.00





