

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS3/GRB21007017/Bqf3-1 Date: 11/01/2022 Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLS 5230C	Veh. Inspected	GBG 4166T
Policy No.	D21MFL0000447	Coverage (\$)	0.00
Claim No.	MFL2021D0002694	Excess (\$)	0.00
Assign From	CARINE KEK PHER SER	Assign Date	07/12/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PROACE	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	YARVFAHKHGZ069481	Colour	WHITE
Odometer	44782 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/65 R16	GOODYEAR	5 mm
L/H Front Tyre	215/65 R16	GOODYEAR	5 mm
R/H Rear Tyre	215/65 R16	BRIDGESTONE	5 mm
L/H Rear Tyre	215/65 R16	BRIDGESTONE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/06/2021	Inspection Date	29/06/2021
Survey held at	SIN HENG LONG MOTOR WORK BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-287/305 SINGAPORE 569535		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	