



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4166T

| Qty                                | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |               |                           |                   |
| 1                                  | FRONT FENDER RH   | DENTED        | 1,444.00                  | 1,444.00          |
| 1                                  | FRONT FENDER INNER SHIELD RH  | NOT DAMAGED   | 195.00                    | -                 |
| 1                                  | FRONT DOOR RH   | DENTED        | 2,400.00                  | 2,400.00          |
| 1                                  | FRONT DOOR GLASS OUTER MOULDING   | NECESSARY     | 192.00                    | 192.00            |
| 1                                  | FRONT DOOR GLASS REGULATOR  | BENT          | 285.70                    | 285.70            |
| 1                                  | FRONT DOOR GLASS REGULATOR MOTOR  | NOT DAMAGED   | 355.20                    | -                 |
| 1                                  | FRONT DOOR OUTER LOCK HANDLE  | NOT DAMAGED   | 192.00                    | -                 |
| 1                                  | FRONT DOOR KEY LOCK   | NOT DAMAGED   | 235.40                    | -                 |
| 1                                  | FRONT DOOR LOCK   | NOT DAMAGED   | 214.00                    | -                 |
| 1                                  | FRONT DOOR INNER TRIM BOARD RH  | BROKEN        | 256.80                    | 256.80            |
| 1                                  | FRONT DOOR PROTECTOR RH   | CUT           | 125.00                    | 125.00            |
| 1                                  | FRONT DOOR WEATHERSTRIP VERTICAL RH   | NOT DAMAGED   | 149.80                    | -                 |
| 1                                  | FRONT DOOR SIDE MIRROR INNER GARNISH RH   | NOT DAMAGED   | 58.00                     | -                 |
| 1                                  | FRONT DOOR INNER TRIM BOARD GARNISH RH  | BROKEN        | 110.00                    | 110.00            |
| 1                                  | FRONT DOOR GLASS CONTROL SWITCH RH  | NOT DAMAGED   | 115.20                    | -                 |
|                                    | LESS 25% DISCOUNT   |               | -                         | -1,203.38         |
|                                    |   |               | 6,328.10                  | 3,610.12          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |               |                           |                   |
| 1                                  | DOOR SPEAKER (SN)   | NOT DAMAGED   | 180.30                    | -                 |
| 1                                  | DOOR LTA STICKER (SN)   | NECESSARY     | 25.00                     | 25.00             |
| 1                                  | SET DOOR INNER TRIM BOARD CLIPS (SN)  | NECESSARY     | 30.00                     | 30.00             |
| 1                                  | SET FENDER INNER SHIELD CLIPS (SN)  | NOT NECESSARY | 25.00                     | -                 |
|                                    |   |               | 260.30                    | 55.00             |
| <b><u>LABOUR</u></b>               |   |               |                           |                   |
|                                    | TO STRAIGHTEN AND PANEL BEATING FRONT DOOR PILLAR RH, REAR DOOR RH, FRONT BUMPER AND FRONT RH FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS. |               | 1,200.00                  | 600.00            |
|                                    | TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.  |               | 1,600.00                  | 600.00            |
|                                    | TO CHECK AND RECTIFY WIRING SYSTEM.   | NOT NECESSARY | 80.00                     | -                 |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty   | Description of Parts                          | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
|   | TO REMOVE AND REFIT FRONT DOOR RH COMPONENTS. | NOT NECESSARY | 150.00                    | 80.00             |
|   | TO RUST AFFECTED AREAS.                       |               | 120.00                    | -                 |
|   |   |               | 3,150.00                  | 1,280.00          |
| <b>GRAND TOTAL</b>  |   |               | <b>9,738.40</b>           | <b>4,945.12</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |   |               |                           | <b>3,900.00</b>   |

Report Ref No. CS3/GRB21007017/Bqf3e2-1

LIM TEOW GUAN

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.