



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|-------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|----------------------------|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR21012382/Aqf3n2 | |
| | | | Date: 15/03/2022 | |
| | | | Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHB 776P | Veh. Inspected | SKL 6686M |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | TAX/11/21/2065 | Excess (\$) | 0.00 |
| | Assign From | HUA YEN | Assign Date | 07/12/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | BMW 528I | c.c | 1997 |
| | Engine No. | HIDDEN | Year of Reg. | 2013 |
| | Chassis No. | WBA5A52070D284682 | Colour | WHITE |
| | Odometer | 72506 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 245/45 R18 | GOODYEAR | 6 mm |
| | L/H Front Tyre | 245/45 R18 | GOODYEAR | 6 mm |
| | R/H Rear Tyre | 245/45 R18 | GOODYEAR | 6 mm |
| | L/H Rear Tyre | 245/45 R18 | GOODYEAR | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 30/11/2021 | Inspection Date | 08/12/2021 |
| | Survey held at | No. 8 KAKI BUKIT AVE 4 @ PREMIER @02-13 | | |
| | Repairer | AUTO MEGA MALL PTE LTD | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |