

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : MSIG INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	
Policy No:	5121974557	Date of Loss:	02/12/2021
Vehicle Reg. No.:	SLN6761G	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SLQ4011K
Any Injuries?	no	Contact No:	
Insured/Claimant:	WU ZHIHUI, ALLEN	Driver:	LING YUQI EUNICE

PARTS MODEL

Make/Model:	Kia, Cerato - KNAFE242	Vehicle Reg. Date:	15.05.2017
Vehicle Colour:	white	Engine Number:	G4FGGH667609
Chassis No:	KNAFX411MH5696778	Odometer:	-
Total Loss?	-	Est. Duration of Repair(Day)	10

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss REFER TO GIA REPORT

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	6,718.96
Miscellaneous Items	340.00
Labour	1,210.00
Paintwork Labour	1,050.00
Towing	0.00
Gross Total(S\$):	9,318.96
GST 7.00%(S\$):	652.33
Nett Amount(S\$):	9,971.29

This claim is handled by: Tee Shu yi

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER <i>de</i>	767.80	-20.00	614.24 ✓
2	1	REAR BUMPER LOWER SKIRT <i>de</i>	260.50	-20.00	208.40 ✓
3	1	REAR BUMPER REFLECTOR RH <i>Xan</i>	121.50	-20.00	97.20 X
4	1	REAR BUMPER REFLECTOR LH <i>cr</i>	121.50	-20.00	97.20 ✓
5	1	REAR BUMPER SIDE RETAINER RH <i>Xan</i>	35.10	-20.00	28.08 X
6	1	REAR BUMPER SIDE RETAINER LH <i>cr</i>	35.10	-20.00	28.08 ✓
7	1	REAR BUMPER BRACKET RH <i>Xan</i>	81.50	-20.00	65.20 X
8	1	REAR BUMPER BRACKET LH <i>Xan</i>	81.50	-20.00	65.20 X
9	1	REAR BUMPER REINFORCEMENT <i>Xan</i>	315.70	-20.00	252.56 X
10	1	REAR BUMPER INNER SPONGE <i>Xan</i>	168.70	-20.00	134.96 X
11	1	REAR BUMPER REINFORCEMENT SMART KEY SENSOR <i>Xan</i>	153.20	-20.00	122.56 X
12	1	REAR BUMPER LOWER COVER RH <i>Xan</i>	124.80	-20.00	99.84 X
13	1	REAR BUMPER LOWER COVER LH <i>de</i>	124.80	-20.00	99.84 ✓
14	1	REAR BOOT LID <i>Xan</i>	963.60	-20.00	770.88 X
15	1	REAR BOOT LID HINGE RH <i>Xan</i>	110.10	-20.00	88.08 X
16	1	REAR BOOT LID HINGE LH <i>Xan</i>	110.10	-20.00	88.08 X
17	1	REAR BOOT LID RUBBER <i>Xan</i>	132.80	-20.00	106.24 X
18	1	REAR BOOT LID LAMP RH <i>Xan</i>	711.20	-20.00	568.96 X
19	1	REAR BOOT LID LAMP LH <i>Xan</i>	711.20	-20.00	568.96 X
20	1	REAR BOOT LID LOCK <i>Xan</i>	111.50	-20.00	89.20 X
21	1	REAR END PANEL <i>Xan</i>	321.20	-20.00	256.96 X
22	1	REAR END PANEL INNER GARNISH <i>Xan</i>	104.80	-20.00	83.84 X
23	1	REAR END PANE KEYLESS SENSOR <i>Xan</i>	162.10	-20.00	129.68 X
24	1	REAR SPARE TYRE PANEL <i>Xan</i>	717.40	-20.00	573.92 X
25	1	REAR SPARE TYRE BOARD <i>Xan</i>	162.80	-20.00	130.24 X
26	1	REAR TAILLAMP RH <i>Xan</i>	844.10	-20.00	675.28 X
27	1	REAR TAILLAMP LH <i>Xan</i>	844.10	-20.00	675.28 X
Total Parts (S\$)					6,718.96

1047.76

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS <i>cr</i>	45.00	0.00	45.00 <i>30</i>
2	1	REAR SENSOR <i>scr</i>	250.00	0.00	250.00 <i>200</i>
3	1	REAR END PANEL INNER GARNISH CLIPS <i>Xan</i>	45.00	0.00	45.00 X
Sub Total (S\$)					340.00

230

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 <i>80 Xan</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>60</i>
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 ✓
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and	1,000.00	0.00	1,000.00 <i>300</i>

Estimates On Labour

Qty	Particulars	Amount	%Disc	After Disc
-----	-------------	--------	-------	------------

Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.

390

Gross Labour Cost (\$\$) 1,210.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
-----	-----	-------------	--------	-------	------------

1 1 To Carry-Out Body Cavity Preservation.

50.00

0.00

50.00

2 1 To Supply Spray Terostat Sealant On The Cutting Areas.

100.00

0.00

100.00

3 1 To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.

100.00

0.00

100.00

4 1 To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.

800.00

0.00

800.00

200
200
200

Gross Labour Cost (\$\$) 1,050.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resu
Hp 90010068

3 days

4/5

08/12/21 @ 1030

Resurvey after repair

1047.76

230.00

390.00

200.00

1867.76

20%

1494.20

4/5 - \$1,450