

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21012388/EQF3N2**Date:** 27/12/2021**REFERENCE**

Insured/Claimant:	LIM AGNES	Policy No:	1800101326	
Date of Loss:	05/12/2021	Nature of Claim:	OD	Claim No: 8195243468SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD5517T	Engine No:	G4FGJH702640
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5011273
Reg. Date:	27/08/2018 (Man. Year: 2018)	Odometer:	47568 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,589.00	804.00	785.00	49.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	960.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,549.00	1,764.00	785.00	30.80
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	2,249.00	1,464.00	785.00	34.90
+ GST 7.00/7.00% (S\$)	157.43	102.48	54.95	34.90
Nett Amount (S\$)	2,406.43	1,566.48	839.95	34.90

INSPECTION

Date of Assignment:	07/12/2021	
Date Inspected:	08/12/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER	Crushed	651.00 F	*651.00 FL
2	1		*COVER-RR BUMPER LWR	Broken	241.00 F	*241.00 FL
3	1		*COVER-RR BUMPER FOG LAMP,LH	Cut	88.00 F	*88.00 FL
4	1		*LAMP ASSY-SIDE T/SIGNAL,LH	Not Necessary	181.00 F	*- FL
5	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Not Necessary	25.00 F	*- FL
6	1		*BEAM-RR BUMPER	Not Necessary	318.00 F	*- FL
7	1		*STAY-RR BUMPER,LH	Not Necessary	65.00 F	*- FL
8	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,589.00	1,000.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	196.00
Total Parts (\$\$)	1,589.00	804.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR LOWER BUMPER,REPAIR REAR BUMPER	New	400.00	400.00
2	SPRAY PAINT FOR REAR BUMPER	New	350.00	350.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			960.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >