

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21012389/UTY3E2

Date: 22/12/2021

REFERENCE

Insured/Claimant: LOH YAO KANG, KESTER Policy No: DMPCSNW00060302100

Date of Loss: 28/11/2021

Nature of Claim: OD

Claim No: SNM21D206910/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP594P**
Make & Model: MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A) Engine No: 27091030888789
Reg. Date: 28/03/2016 (Man. Year: 2015) Chassis No: WDD1760422J437030
Colour: Purple Odometer: 0 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35Z R19 Rear Tyre Size: 235/35Z R19
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	500.00	0.00	500.00	100.00
Nett Amount (\$\$)	-500.00	0.00	-500.00	100.00

INSPECTION

Date of Assignment: 07/12/2021 Present Location: Car City Auto Centre Pte Ltd (HQ)
Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 08/12/2021 Inspected At: Blk 9006 #01-198, Tampines Street 93
Singapore 528840
Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$66,000.00
OMV :	\$23,253.00
PARF Rebate (1) :	\$13,688.00
Quota Premium Paid :	\$43,000.00
COE Rebate (2) :	\$18,506.00
Total Rebate (1) + (2) = :	\$32,194.00

The total amount incurred will be Market Value \$66,000.00 minus Total Rebate \$32,194.00 = \$33,806.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2021)
Parts:	144	MERCEDES-BENZ A180 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP594P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >