

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012392/ATY3N2**Date:** 25/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00005682100		
Claimant Vehicle No :	SMV1753J	Insured Vehicle No :	SNA8076H		
Date of Loss:	06/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207089/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV1753J		
Make & Model:	MERCEDES-BENZ C180K, 1.6 (A)	Engine No:	27191031343733
Reg. Date:	20/01/2011 (Man. Year: 2010)	Chassis No:	WDD2040452A499479
Colour:	Black	Odometer:	165083 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,865.50	1,852.50	1,013.00	35.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	580.00	1,360.00	70.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,805.50	2,432.50	2,373.00	49.38
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	4,805.50	1,900.00	2,905.50	60.46
+ GST 7.00/7.00% (S\$)	336.39	133.00	203.39	60.46
Nett Amount (S\$)	5,141.89	2,033.00	3,108.89	60.46

INSPECTION

Date of Assignment:	08/12/2021		
Date Inspected:	07/12/2021	Inspected At:	23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933 REPAIRER: SK AUTOMOBILE PTE LTD
Estimated Period of Repair:	2.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2022)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV1753J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR TAILLAMP LOWER BRACKET LH/RH	Not Necessary	190.00 FL	*- FL
2	2		*REAR FENDER TOP GARNISH LH/RH	Not Necessary	90.00 FL	*- FL
3	10		*REAR FENDER TOP GARNISH CLIPS LH/RH	Not Necessary	180.00 FL	*- FL
4	1		*REAR BUMPER	Deformed	1,615.00 FL	*1,615.00 FL
5	1		*REAR BUMPER CHROME MOULDING CENTER	Necessary	140.00 FL	*140.00 FL
6	2		*REAR BUMPER CHROME MOULDING LH/RH	Necessary	270.00 FL	*270.00 FL
7	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	110.00 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
9	1		*REAR BUMPER REVERSE SENSOR SET (4 EYES)	Not Necessary	450.00 FS	*- FS
					Sub Total (\$\$)	3,125.00 2,055.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	259.50 202.50
					Total Parts (\$\$)	2,865.50 1,852.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	500.00	250.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	500.00	250.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
4	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	150.00	50.00
5	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	0.00
6	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	0.00
7	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (\$)			1,940.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >