

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012397/AGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100491704
Claimant Vehicle No :	SMK5358Z	Insured Vehicle No :	SFE12T
Date of Loss:	04/12/2021	Nature of Claim:	TP
		Claim No:	2972951169SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5358Z	Engine No:	L15B6001734
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82001416
Reg. Date:	15/04/2019 (Man. Year: 2019)	Odometer:	26753 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,576.56	9,472.56	7,104.00	42.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,990.00	2,980.00	5,010.00	62.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,566.56	12,452.56	12,114.00	49.31
Approved Total (Overridden) (S\$)		9,900.00		
Nett Amount (S\$)	24,566.56	9,900.00	14,666.56	59.70
+ Loss of Use (11.0 x S\$50.00/day) (S\$)		550.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		10,546.45		
Global Sum Settlement (S\$)		10,500.00		

INSPECTION

Date of Assignment:	07/12/2021	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	07/12/2021 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	9.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,150.60 FL	*1,150.60 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	87.60 FL	*- FL
3	1		*REAR BUMPER REFLECTOR GARNISH	N/S Deformed	90.20 FL	*45.10 FL
4	1		*REAR BUMPER TOWING COVER	Not Necessary	19.00 FL	*- FL
5	2		*REAR BUMPER SIDE INNER GARNISH	Torn	196.80 FL	*196.80 FL
6	2		*REAR BUMPER SIDE RETAINER	Necessary	53.00 FL	*53.00 FL
7	1		*REAR BUMPER EXHAUST GARNISH	Not Necessary	39.60 FL	*- FL
8	2		*REAR BUMPER SPONGE	Not Necessary	94.00 FL	*- FL
9	1		*TAIL GATE	Distorted	1,193.40 FL	*1,193.40 FL
10	1		*TAIL GATE OUTER GARNISH C/W MOULDING (CHROME)	Cracked	383.20 FL	*383.20 FL
11	2		*TAIL GATE NUMBER PLATE LAMP	Not Necessary	77.00 FL	*- FL
12	1		*TAIL GATE LOGO	Necessary	38.20 FL	*38.20 FL
13	1		*TAIL GATE EMBLEM SHUTTLE	Necessary	55.70 FL	*55.70 FL
14	1		*TAIL GATE EMBLEM HYBRID	Necessary	120.00 FL	*120.00 FL
15	2		*TAIL GATE LAMP	Cracked	790.00 FL	*790.00 FL
16	2		*TAIL GATE DAMPER	Not Necessary	208.20 FL	*- FL
17	2		*TAIL GATE HINGE	Not Necessary	91.20 FL	*- FL
18	1		*TAIL GATE INNER HOLDER	Not Necessary	27.50 FL	*- FL
19	2		*TAIL GATE STOPPER	Not Necessary	38.00 FL	*- FL
20	1		*TAIL GATE INNER LOCK	Damaged	256.40 FL	*256.40 FL
21	1		*TAIL GATE LOCK CATCH	Not Necessary	24.00 FL	*- FL
22	1		*TAIL GATE WEATHER STRIP	Cut	168.10 FL	*168.10 FL
23	1		*TAIL GATE DETECTOR	Not Necessary	296.00 FL	*- FL
24	1		*TAIL GATE DETECTOR WIRE HARNESS	Not Necessary	436.40 FL	*- FL
25	1		*TAIL GATE INNER TRIM	Cracked	320.00 FL	*320.00 FL
26	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	150.10 FL	*150.10 FL
27	1		*REAR BUZZER	Not Necessary	124.30 FL	*- FL
28	2		*TAIL LAMP	Cut	1,041.00 FL	*1,041.00 FL
29	2		*TAIL LAMP LOWER PANEL	Dented	470.40 FL	*470.40 FL
30	2		*REAR FENDER COWLING	Not Necessary	295.60 FL	*- FL
31	2		*REAR FENDER INNER TRIM	Cracked	1,100.00 FL	*978.00 FL
32	1		*FUEL TANK COVER GARNISH	Not Necessary	798.00 FL	*- FL
33	1		*REAR END PANEL	Distorted	601.20 FL	*601.20 FL
34	1		*REAR END PANEL TOP GARNISH	Deformed	155.50 FL	*155.50 FL
35	1		*REAR FLOOR PANEL	Distorted	1,010.00 FL	*1,010.00 FL
36	1		*REAR FLOOR PANEL TOP OUTER BOARD	Deformed	585.00 FL	*336.00 FL
37	1		*REAR FLOOR PANEL TOP INNER BOARD	Not Necessary	469.00 FL	*- FL
38	2		*REAR FLOOR PANEL TOP SIDE BOARD	Not Necessary	300.00 FL	*- FL
39	1		*REAR STORAGE BOX (PLASTIC)	Cracked	495.00 FL	*358.00 FL
40	1		*REAR TOOLS SPONGE TRAY	Deformed	285.00 FL	*285.00 FL
41	1		*REAR JACK COVER GARNISH	Deformed	190.00 FL	*190.00 FL
42	1		*REAR JACK	Not Necessary	145.00 FL	*- FL
43	1		*REAR CHASSIS MEMBER LH	Repair	694.00 FL	*- FL
44	1		*CENTRE EXHAUST	Repair	1,260.00 FL	*- FL
45	1		*CENTRE EXHAUST INSULATOR	Not Necessary	85.00 FL	*- FL
46	1		*SET CENTRE EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
47	1		*REAR EXHAUST PIPE	Bent	745.00 FL	*745.00 FL
48	1		*REAR EXHAUST INSULATOR	Not Necessary	195.00 FL	*- FL
49	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
50	4		*REAR EXHAUST MOUNTING	Not Necessary	340.00 FL	*- FL
51	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
52	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
53	1		*SET REAR BUMPER REFLECTOR GARNISH CLIP	Not Necessary	60.00 FS	*- FS
54	1		*SET REAR BUMPER SIDE INNER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
55	1		*SET REAR BUMPER EXHAUST GARNISH CLIP	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET TAIL GATE OUTER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
57	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
58	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
59	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
60	1		*SET TAIL LAMP CLIP	Necessary	40.00 FS	*40.00 FS
61	1		*TAIL LAMP LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
62	1		*SET REAR FENDER INNER COWLING	Not Necessary	80.00 FS	*- FS
63	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*60.00 FS
64	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
65	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	350.00 FS	*60.00 FS
66	1		*SET REAR JACK COVER GARNISH CLIP	Necessary	60.00 FS	*10.00 FS
67	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
68	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,158.20	11,690.70
- List Item Discount on L Items 20.00/20.00% (\$)	3,581.64	2,218.14
Total Parts (\$)	16,576.56	9,472.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,400.00	1,400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,200.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
5	REMOVE AND REFIX HYBRIC SYSTEM TO FACILITATE FLOOR PANEL REPLACEMENT	New	800.00	0.00
6	RESET HYBRIC SYSTEM	New	1,800.00	0.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	100.00	0.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	300.00	0.00
			Gross Labour Cost (\$)	7,990.00
				2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >