

TO : **AIG MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SMK5358Z**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : **04.12.2021**
 TIME OF ACCIDENT : **13:40HRS**

27	REAR BUZZER <i>New</i>	1	\$ 124.30	\$ 124.30	+
28	TAIL LAMP <i>cut</i>	2	\$ 520.50	\$ 1,041.00	✓
29	TAIL LAMP LOWER PANEL <i>Distorted</i>	2	\$ 235.20	\$ 470.40	✓
30	REAR FENDER COWLING <i>New</i>	2	\$ 147.80	\$ 295.60	+
31	REAR FENDER INNER TRIM <i>Cracked</i>	2	\$ 550.00	\$ 1,100.00	✓ 978
32	FUEL TANK COVER GARNISH <i>New</i>	1	\$ 798.00	\$ 798.00	+
33	REAR END PANEL <i>Distorted</i>	1	\$ 601.20	\$ 601.20	✓
34	REAR END PANEL TOP GARNISH <i>Delend</i>	1	\$ 155.50	\$ 155.50	✓
35	REAR FLOOR PANEL <i>Distorted</i>	1	\$ 1,010.00	\$ 1,010.00	✓
36	REAR FLOOR PANEL TOP OUTER BOARD <i>Delend</i>	1	\$ 585.00	\$ 585.00	✓ 336.
37	REAR FLOOR PANEL TOP INNER BOARD <i>New</i>	1	\$ 469.00	\$ 469.00	+
38	REAR FLOOR PANEL TOP SIDE BOARD <i>New</i>	2	\$ 150.00	\$ 300.00	+
39	REAR STORAGE BOX (PLASTIC) <i>Cracked</i>	1	\$ 495.00	\$ 495.00	✓ 358
40	REAR TOOLS SPONGE TRAY <i>Delend</i>	1	\$ 285.00	\$ 285.00	✓
41	REAR JACK COVER GARNISH <i>Delend</i>	1	\$ 190.00	\$ 190.00	✓
42	REAR JACK <i>new</i>	1	\$ 145.00	\$ 145.00	+
43	REAR CHASSIS MEMBER LH <i>Reps</i>	1	\$ 694.00	\$ 694.00	+
44	CENTRE EXHAUST <i>Reps</i>	1	\$ 1,260.00	\$ 1,260.00	+
45	CENTRE EXHAUST INSULATOR <i>3/4</i>	1	\$ 85.00	\$ 85.00	+
46	CENTRE EXHAUST GASKET (SET) <i>1/2</i>	1	\$ 60.00	\$ 60.00	+
47	REAR EXHAUST PIPE <i>But.</i>	1	\$ 745.00	\$ 745.00	✓
48	REAR EXHAUST INSULATOR <i>2</i>	1	\$ 195.00	\$ 195.00	+
49	REAR EXHAUST GASKET (SET) <i>1/2</i>	1	\$ 60.00	\$ 60.00	+
50	REAR EXHAUST MOUNTING <i>1/2</i>	4	\$ 85.00	\$ 340.00	+

1109070

887256

TOTAL PRICE \$ 17,908.20
 LESS 20% \$ 3,581.64
SUB TOTAL PRICE \$ 14,326.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>New</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER REFLECTOR GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
4	REAR BUMPER SIDE INNER GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	20
5	REAR BUMPER EXHAUST GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
6	TAIL GATE OUTER GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	20
7	TAIL GATE INNER TRIM CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	30
8	TAIL GATE WINDSCREEN SEALANT <i>3/4</i>	1	\$ 80.00	\$ 80.00	40
9	TAIL GATE WINDSCREEN INNER SEAL <i>1/2</i>	1	\$ 60.00	\$ 60.00	30

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMK5358Z**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 04.12.2021
 TIME OF ACCIDENT : 13:40HRS

10	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	✓
11	TAIL LAMP LOWER PANEL SEALANT <i>New</i>	2	\$ 60.00	\$ 120.00	+
12	REAR FENDER INNER COWLING (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	+
13	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	60
14	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
15	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	60
16	REAR JACK COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10
17	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200
18	REVERSE CAMERA <i>New</i>	1	\$ 550.00	\$ 550.00	600

TOTAL \$ 2,250.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	1400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1200
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
5	REMOVE AND REFIX HYBRIC SYSTEM TO FACILIATE FLOOR PANEL REPLACEMENT	\$ 800.00	x
6	RESET HYBRIC SYSTEM	\$ 1,800.00	x
7	REAR CHASSIS ALIGNMENT	\$ 250.00	x
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
10	REMOVE AND REFIX FUEL TANK TO FACILIATE FLOOR PANEL REPLACEMENT	\$ 100.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 300.00	x

TOTAL \$ 7,990.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,576.56
 TOTAL LABOUR COST : \$ 7,990.00
 TOTAL REPAIR COST : \$ 24,566.56

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMK5358Z**
MODEL : **HONDA SHUTTLE**
DATE OF ACCIDENT : 04.12.2021
TIME OF ACCIDENT : 13:40HRS

CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

Adrian Lj
r/s 07/12/21

09 Days

Total: 12452.56

r/s: 9.8K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: