

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012398/GEA3Q2**Date:** 28/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210020143
Claimant Vehicle No :	SLT1021K	Insured Vehicle No :	GBE7948U
Date of Loss:	02/12/2021	Nature of Claim:	TP
		Claim No:	4404486011SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1021K	Engine No:	1NZR497971
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Chassis No:	NKE1657144644
Reg. Date:	17/10/2017 (Man. Year: 2017)	Odometer:	74857 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,057.85	1,849.65	12,208.20	86.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	1,720.00	2,650.00	60.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,427.85	3,569.65	14,858.20	80.63
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	18,427.85	2,500.00	15,927.85	86.43
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		2,891.00		
Global Sum Settlement (S\$)		2,890.00		

INSPECTION

Date of Assignment:	07/12/2021	PROVI AUTOWORKS PTE LTD (HQ)
Date Inspected:	07/12/2021 Inspected At:	8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Buckled	684.00 FL	*465.20 FL
2	1		*FRONT FENDER COWLING LH	Not Necessary	215.00 FL	*- FL
3	1		*FRONT DOOR LH	Buckled	1,260.00 FL	*1,100.00 FL
4	1		*FRONT DOOR OUTER MOULDING LH	Not Necessary	210.00 FL	*- FL
5	2		*FRONT DOOR FRAME SIDE BLACK STICKER LH	Necessary	134.00 FL	*134.00 FL
6	1		*FRONT DOOR FRAME TOP BLACK STICKER LH	Necessary	75.00 FL	*75.00 FL
7	1		*FRONT DOOR SIDE MIRROR LH	Distorted	1,257.00 FL	*692.00 FL
8	2		*FRONT DOOR HINGE LH	Not Necessary	250.40 FL	*- FL
9	1		*FRONT DOOR CHECKER LH	Not Necessary	89.00 FL	*- FL
10	1		*FRONT DOOR INNER LOCK LH	Not Necessary	417.50 FL	*- FL
11	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	36.00 FL	*- FL
12	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	198.60 FL	*- FL
13	1		*FRONT DOOR FRAME RUBBER LH	Not Necessary	385.00 FL	*- FL
14	1		*FRONT DOOR CHANNEL LH	Not Necessary	98.20 FL	*- FL
15	1		*FRONT DOOR CHANNEL SEAL LH	Not Necessary	178.60 FL	*- FL
16	1		*FRONT DOOR REGULATOR MOTOR LH	Not Necessary	455.60 FL	*- FL
17	1		*FRONT DOOR REGULATOR GEAR LH	Not Necessary	316.70 FL	*- FL
18	1		*FRONT DOOR INNER TRIM LH	Not Necessary	659.90 FL	*- FL
19	1		*FRONT DOOR INNER STEP GARNISH LH	Not Necessary	215.00 FL	*- FL
20	1		*FRONT DOOR OUTER STEP GARNISH LH	Not Necessary	112.00 FL	*- FL
21	1		*CENTER PILLAR OUTER LH	Repair	845.00 FL	*- FL
22	1		*CENTER PILLAR INNER LH	Not Necessary	568.00 FL	*- FL
23	1		*CENTER PILLAR INNER TRIM LH	Not Necessary	485.00 FL	*- FL
24	1		*ROCKER PANEL LH	Repair	845.00 FL	*- FL
25	1		*FRONT LOWER ARM LH	Not Necessary	452.00 FL	*- FL
26	1		*FRONT KNUCKLE ARM LH	Not Necessary	548.00 FL	*- FL
27	1		*FRONT KNUCKLE BEARING LH	Not Necessary	258.00 FL	*- FL
28	1		*FRONT SHOCK ABSORBER LH	Not Necessary	385.00 FL	*- FL
29	1		*REAR DOOR LH	Repair	1,213.60 FL	*- FL
30	2		*REAR DOOR FRAME SIDE BLACK STICKER LH	Not Necessary	137.80 FL	*- FL
31	1		*REAR DOOR FRAME TOP BLACK STICKER LH	Not Necessary	78.30 FL	*- FL
32	1		*REAR DOOR OUTER MOULDING LH	Not Necessary	201.00 FL	*- FL
33	2		*REAR DOOR HINGE LH	Not Necessary	226.00 FL	*- FL
34	1		*REAR DOOR CHECKER LH	Not Necessary	96.70 FL	*- FL
35	1		*REAR DOOR INNER LOCK LH	Not Necessary	426.90 FL	*- FL
36	1		*REAR DOOR LOCK CATCH LH	Not Necessary	36.00 FL	*- FL
37	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	198.00 FL	*- FL
38	1		*DRIVER SEAT BELT	Not Necessary	958.00 FL	*- FL
39	1		*SRS AIRBAG CONTOR UNIT	Not Necessary	1,258.00 FL	*- FL
40	1		*FRONT FENDER SEALANT	Not Necessary	60.00 FS	*- FS
41	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
42	1		*FRONT DOOR SEALANT LH	Not Necessary	60.00 FS	*- FS
43	1		*SET FRONT DOOR INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
44	1		*CENTER PILLAR OUTER SEALANT LH	Not Necessary	60.00 FS	*- FS
45	1		*CENTER PILLAR INNER SEALANT LH	Not Necessary	60.00 FS	*- FS
46	1		*CENTER PILLAR INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
47	1		*ROCKER PANEL SEALANT LH	Not Necessary	60.00 FS	*- FS
48	1		*WHEEL RIM	Not Necessary	800.00 FS	*- FS
49	1		*WHEEL TYRE	Not Necessary	400.00 FS	*- FS
50	1		*REAR DOOR SEALANT LH	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,173.80	2,466.20
- List Item Discount on L Items 25.00/25.00% (\$)	4,115.95	616.55
Total Parts (\$)	14,057.85	1,849.65

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	1,000.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	250.00	0.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	200.00	60.00
5	REMOVE AND INSTALL FRONT DOOR PART	New	250.00	60.00
6	REMOVE AND INSTALL REAR DOOR PART	New	250.00	0.00
7	REMOVE AND INSTALL FRONT UNDERCARRIAGE	New	500.00	0.00
8	4 WHEEL WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$)			4,370.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >